

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA TAIPING	DATE	: 17/11/2020
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMN4034Z		
MODEL	: HONDA FIT 1.3 A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 14-Nov-20
		TIME	: 15:10HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS (REAR)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 1,122.00	\$ 1,122.00 850
2	TAIL GATE LOGO <i>New</i>	1	\$ 58.00	\$ 58.00
3	TAIL GATE EMBLEM 'FIT' <i>New</i>	1	\$ 58.00	\$ 58.00
4	TAIL GATE DETECTOR <i>3 cracked</i>	1	\$ 155.30	\$ 155.30 89
5	TAIL GATE BUZZEL	1	\$ 180.00	\$ 180.00 87
6	TAIL GATE INNER LOCK <i>New</i>	1	\$ 225.80	\$ 225.80
7	TAIL GATE WEATHER STRIP <i>cut</i>	1	\$ 128.00	\$ 128.00
8	TAIL GATE WINDSCREEN MOULDING <i>New</i>	1	\$ 190.00	\$ 190.00
9	REAR BUMPER <i>Dented</i>	1	\$ 730.00	\$ 730.00 485
10	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 42.00	\$ 84.00
11	REAR BUMPER CENTRE GARNISH <i>Dented</i>	1	\$ 230.00	\$ 230.00
12	REAR END PANEL <i>Dented</i>	1	\$ 520.00	\$ 520.00 378
13	REAR END PANEL TOP GARNISH <i>cracked</i>	1	\$ 190.00	\$ 190.00

TOTAL PRICE \$ 3,871.10
LESS 20% \$ 774.22
SUB TOTAL PRICE \$ 3,096.88

2779

2223.20

SPECIAL NETT ITEMS (REAR)

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	TAIL GATE WINDSCREEN SEALANT <i>Nlu</i>	1	\$ 80.00	\$ 80.00 <i>60</i>
2	REAR BUMPER CLIP(SET) <i>Nlu</i>	1	\$ 20.00	\$ 20.00 <i>-</i>
3	REAR END PANEL TOP GARNISH CLIPS <i>Nlu</i>	1	\$ 20.00	\$ 20.00 <i>-</i>
4	REAR END PANEL INSULATION SEAL <i>Nlu</i>	1	\$ 120.00	\$ 120.00 <i>60</i>
5	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 <i>200</i>

360

TOTAL \$ 460.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	<i>200</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>800</i>	
3	TUFF COAT	\$ 250.00	<i>60</i>	
4	WIRING CHECK	\$ 80.00	<i>30</i>	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>	
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>	
7	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>	
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	<i>✓</i>	

TOTAL \$3,090.00

1890

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,556.88
 TOTAL LABOUR COST : \$ 3,090.00
 TOTAL REPAIR COST : \$ 6,646.88

Adrian Lj
L/S 18/11/20

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

06 days

total: 4573.20

L/S: 3.6K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: