

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLD 6376M*

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

056

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

179B

Vehicle: IN / OUT

Date: Person Contacted:

Dep 803

Date / Time

Action / Instruction

*have video at fold
N2 B2 LTA 045888
net 10/12*

24/11/20 confirmed n/s \$ 6200 with David

Veh No:

SLD 6376M

Yr Regn:

24/6/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAI

Make:

Toyota corolla AHS c.c 1598

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

35603

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053REH104550 608

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Inorder~~ / Jammed / Leaked / Burnt or

other

Brake: ~~Inorder~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

17/11/20

D.O.I.

18/11/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I.: (\$

)

TOTAL

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3010/11/20 Your Ref: Date: 18th NOV 2020

MS TEO HUI
31, Pasir Ris Drive 3,
#02-04, S (519491)

Estimate cost of repair to TOYOTA COROLLA ALTIS 1.6 (A) Saloon - SLD 6376 M

1 pc front bumper	De/moped	\$ 458.10
1 pc front bumper o/s side retainer	CRA	62.90
1 set front bumper clips	NEC	32.80
1 pc o/s head lamp assy	CRA	2,223.10
1 pc front o/s fender	30.5 DD	761.50
1 pc front o/s fender 'VVTi' emblem	NEC	39.70
1 pc front o/s fender inner shield	DIS	236.70
1 set front o/s fender inner shield clips	NEC	24.00
1 pc front o/s fender top garnish	11	89.30 X
1 pc front o/s door	30.5 DD	1,079.60
1 pc front o/s door top hinge	11	82.80 X
1 pc front o/s door lower hinge	11	82.80 X
1 pc front o/s door weatherstrip	NEC	157.70
1 pc front o/s door checker	11	138.30 X
1 pc front o/s door glass regulator	11	268.80 X
1 pc front o/s door glass channel case	11	81.70 X
1 pc front o/s door glass channel	11	147.30 X
1 set front o/s door frame sticker	NEC	71.90
16 pcs front o/s door inner trim board clips	4.20 11	67.20 X
1 pc front o/s shock absorber shaft	30.5	482.90
1 pc front o/s lower arm	30.5	459.30
1 pc front o/s knuckle arm	30.5	441.40
1 pc front o/s wheel bearing	NEC	119.40
1 pc front o/s trading arm	30.5	180.50 X
1 pc front o/s sport rim	CRA	1,394.80
		6005/w
		\$ 9,184.50
Less 25%		\$ 2,296.13
		\$ 6,888.37

To check & adjust front wheel alignment & balancing. 150.00 80

To wiring check up for affected wiring system. 50.00 20

To remove & refix front o/s door trim board, inner lock, handle, garnish, glass, moulding, regulator, motor, channel, weatherstrip hinge & necessary parts into new door. 200.00 60

Labour charge to remove & refix front o/s shock absorber shaft, lower arm, knuckle arm, bearing & necessary parts, including pump the wheel bearing by mechanic. 300.00 120

\$ 7,588.37

Balance C/F.....

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3010/11/20

Your Ref: _____

Date: 23rd NOV 2020

MS TEO HUI

31, Pasir Ris Drive 3,
#02-04, Singapore 519491

SUPPLEMENTARY Bill for TOYOTA COROLLA ALTIS 1.6 (A) Saloon - SLD 6376 M

1 pc front o/s wheel ABS sensor (Speed)

shared

\$ 362.10 ✓

Less 25% \$ 90.53

\$ 271.57

To diagnose & re-set ABS (Speed) sensor, using computer.

150.00 *60*

\$ 421.57

=====

Dollars : Four Hundred Twenty One And Cents Fifty Seven Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

P- 7013.1

252

P- 5259.82

SN-600

L- 1900

7759.82

2m

6207

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3010/11/20 Your Ref: Date: 18th NOV 2020

MS TEO HUI.,

Balance B/F.... \$ 7,588.37

To remove & refix carpet, floor mat, door pillar garnish & necessary parts, to enable repair front o/s door pillar panel & necessary parts.

11 100.00 X

To respray Tuff-Kote on all affected accident parts.

90.00 60

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front o/s door pillar panel & necessary parts, to weld, renew & align above parts.

1,500.00 600

To putty & respray painting on all affected accident parts.

1,400.00 900

\$ 10,678.37
=====

Dollars : Ten Thousand Six Hundred Seventy Eight And Cents Thirty Seven Only.

HUP MOTOR TRADING & SERVICE

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: