

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20012687/KBA3Q2

**Date:** 17/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070008759

**Claimant**  
**Vehicle No :** SHD401K **Insured Vehicle No :** SLE6777J

Date of Loss: 15/11/2020 Nature of Claim: TP Claim No: 2268534346SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD401K**  
 Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Engine No: M9R8839C003391  
 Reg. Date: 17/10/2016 (Man. Year: 2016) Chassis No: VF1ABL15AUC283412  
 Colour: Metallic White/Red Odometer: 662594 km  
 Engine Capacity: 1995 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
 Front Left Side: Sailun 8 mm Rear Left Side: Sailun 8 mm  
 Front Right Side: Sailun 8 mm Rear Right Side: Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,482.73	1,604.31	6,878.42	81.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,070.00	490.00	6,580.00	93.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,552.73</b>	<b>2,094.31</b>	<b>13,458.42</b>	<b>86.53</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,700.00</b>		
<b>(S\$)</b>	15,552.73	1,700.00	13,852.73	89.07
<b>+ GST 7.00/7.00% (S\$)</b>	1,088.69	119.00	969.69	89.07
<b>Nett Amount (S\$)</b>	<b>16,641.42</b>	<b>1,819.00</b>	<b>14,822.42</b>	<b>89.07</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$99.13/day) (S\$)</b>		198.26		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>2,124.75</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,100.00</b>		

### INSPECTION

Date of Assignment: 17/11/2020

Date Inspected: 17/11/2020 Inspected At:

Trans-cab Auto Services Pte Ltd  
 No 2 Ang Mo Kio Street 63  
 Singapore 569111

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented/Distorted	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
7	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
8	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
9	1		*BUMPER BEAM BRACKET LH REAR	Distorted	114.50 FL	*114.50 FL
10	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	*- FL
11	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
12	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
13	1		*BOOT REAR	Repair	1,677.20 FL	*- FL
14	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
15	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
16	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
17	1		*BOOT HINGE RH	Repair	254.20 FL	*- FL
18	1		*BOOT LOCK	Repair	246.60 FL	*- FL
19	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
20	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
21	1		*BOOT BADGE RENAULT	Not Necessary	82.40 FL	*- FL
22	1		*BOOT BADGE	Not Necessary	95.80 FL	*- FL
23	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
24	1		*TAILLAMP RH	Serviceable	401.40 FL	*- FL
25	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
26	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
27	1		*BOOT FINISHER NUT L70Y	Not Necessary	60.00 FS	*- FS
28	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
29	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
30	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
31	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
32	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
33	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
34	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
35	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
36	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
37	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	120.00 FS	*- FS
38	1		*REAR BOOT STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
39	1		*REAR BOOT STICKER 6555-3333	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>9,280.28</b>	<b>1,767.90</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	797.55	163.59
<b>Total Parts (S\$)</b>	<b>8,482.73</b>	<b>1,604.31</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,000.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,070.00</b>	<b>490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >