

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0888/2020/NS
DATE	:	19-Nov-20
WIP	:	58076

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SJL 653 J

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MS MALATHI D/O MUTHU VERAN
ADDRESS	:	BLK 410 BEDOK NORTH AVE 2
		#07-76
		SINGAPORE 460410
TELEPHONE	:	HP +65 97377472
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	1800109793-01
VEHICLE NO	:	SME 177 T
MODEL CODE	:	AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR	:	14/9/2018
ENGINE NO	:	CVK 068599
CHASSIS NO	:	WAUZZZF53JA134014
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	18-Nov-20
PLACE OF ACCIDENT	:	BEDOK NORTH ROAD



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SME 177 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓	\$ 2,400.00	1000
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET. X	\$ 3,000.00	1100
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,552.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 177 T

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER new ?		\$ 2,251.00	new ?
2 FRONT BUMPER FIXING PARTS new		\$ 402.00	+
3 FRONT BUMPER SECURING STRIP ? 2		\$ 70.00	?
4 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE new		\$ 225.00	+
5 FRONT BUMPER AIR GUIDE - LH new		\$ 62.00	X
6 FRONT BUMPER AIR GUIDE GRILLE - LH new		\$ 468.00	+
7 FRONT BUMPER GUIDE SECTION - LH ?		\$ 36.00	?
8 FRONT FENDER - LH Dented		\$ 1,048.00	✓
9 FRONT FENDER ATTACHMENT PARTS new		\$ 53.00	+
10 FRONT FENDER CLOSING ELEMENT - LH ?		\$ 73.00	?
11 FRONT FENDER BRACKET - LH ?		\$ 35.00	?
12 FRONT FENDER BRACKET - INNER ?		\$ 35.00	?
13 FRONT FENDER BRACE - LH ?		\$ 117.00	?
14 WHEEL HOUSING LINER - LH Not new		\$ 272.00	X
15 WHEEL HOUSING LINER ATTACHMENT PARTS new		\$ 90.00	+
16 WHEEL SPOILER Not new		\$ 73.00	+
17 WHEEL SPOILER TRIM - LH new		\$ 35.00	+
18 STONE CHIP GUARD - LH new		\$ 50.00	✓
19 FRONT FENDER TRIM - LH new		\$ 157.00	✓
20 TOP FENDER LEDGE COVER - UPPER ?		\$ 35.00	?
SUB TOTAL SPARE PARTS	:	\$ 5,587.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 177 T

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 TOP FENDER LDGE COVER - LOWER ?	\$	16.00	?
22 FRONT ALUMINIUM RIM - LH <i>cut</i>	\$	1,012.00	✓
23 LED HEADLIGHT - LH <i>Not Alter</i>	\$	7,812.00	+
24 BONNET IMPACT PROTECTION - CENTRE ?	\$	27.00	+
25 BONNET IMPACT PROTECTION - LH <i>NAH</i>	\$	28.00	+
26 BONNET IMPACT PROTECTION - RH <i>NAH</i>	\$	27.00	+
27 SUNDRIES ?	\$	300.00	?
TOTAL SPARE PARTS	:	\$ 14,809.00	
TOTAL LABOUR CHARGES	:	\$ 6,552.00	
GRAND TOTAL	:	\$ 21,361.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *20/11/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 05 days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT