

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

GW1453R

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES2090937/YISHUN
Date: 19 Nov 2020
Policy No: 20-MU010292-R03
Veh Reg No: GW1453R
Make/Model: TOYOTA TOYOTA
LITEACE 5 DR
Chassis No: CR425004805
Engine No: 3C3969134
Reg. Date: 24/03/2003

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 16/11/2020
TP Veh Reg No: GBH7542R

*Not Authorized
1/15mp & 4150p
Respray After Paint
8 days*

Estimate Repair Cost to Vehicle No :GW1453R

PAGE: 1/1

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	429.20	1 PC	429.20	✓
2 REAR BUMPER RH SIDE RETAINER	39.80	1 PC	39.80	✓
3 REAR BUMPER RH REFLECTOR	47.60	1 PC	47.60	✓
4 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
5 REAR TAILGATE	1,153.20	1 PC	1,153.20	✓
6 TAILGATE INNER RUBBER	273.40	1 PC	273.40	✓
7 REAR WINDSCREEN GLASS MOULDING	79.90	1 PC	79.90	✓
8 REAR RH SIDE PANEL	1,147.40	1 PC	1,147.40	✓
9 RH SLIDING DOOR TRACK	246.80	1 PC	246.80	✓
10 RH TAILLAMP	246.00	1 PC	246.00	✓
11 REAR END PANEL OUTER	416.70	1 PC	416.70	✓
			4,101.00	
		Less 25%	1,025.25	3,075.75
Special Net				
12 STICKER - 70KM/H	10.00	1 PC	10.00	✓
13 STICKER - 5 PAX	10.00	1 PC	10.00	✓
14 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
			60.00	60.00
Labour				
15 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
16 REMOVE & REFIX REAR SEAT CUSHION, CARPET, REAR SPEAKER & TRIMBOARD, FLOORBOARD & REALIGN THE SAME	280.00	1 LA	280.00	15d
17 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, TAILGATE & ATTACHMENT, REAR SLIDING TRACK, RH SLIDING DOOR, TO CUT, WELD & RENEW REAR END PANEL OUTER, REAR RH SIDE PANEL, KNOCK & REPAIR INNER PANEL & REALIGN THE	1,500.00	1 LA	1,500.00	120d
18 PUTTY & RESPRAY ON REAR FLOORBOARD PANEL, REAR END PANEL, RH REAR SIDE PANEL & ALL AFFECTED AREAS	1,000.00	1 LA	1,000.00	80d
19 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,960.00	2,960.00
			Total	SS 6,095.75
			Add GST @ 7%	426.70
			Total Amount Payable	SS 6,522.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

\$5198.98

4/5 \$4150/

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Supp 1

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 16/11/2020
TP Veh Reg No: GBH7542R

Estimate No: ES2090937 /YISHUN
Date: 23 Nov 2020
Policy No: 20-MU010292-R03
Veh Reg No: GW1453R
Make/Model: TOYOTA TOYOTA
LITEACE 5 DR
Chassis No: CR425004805
Engine No: 3C3969134
Reg. Date: 24/03/2003

Estimate Repair Cost to Vehicle No :GW1453R

PAGE:1/1

<u>Estimate Repair Cost to Vehicle No. GW1455X</u>				
Description	U/Price	Quantity	List Price <u>S\$</u>	Amount <u>S\$</u>
Supplementary 1				
1 List Price				
REAR RH FENDER INNER AIR-SCOOP GRILLE	<i>mjcm</i> 61.00	1 PC	61.00 ✓	
		Less 25%	15.25	45.75
		Total		S\$ 45.75
		GST Amount		S\$ 3.20
		Total Amount Payable		S\$ 48.95

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE