

XINYA AUTO SERVICE PTE LTD

Add: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 12-Nov-20

Address : CHIA ENG HUAT
BLK 366 COMPASSVALE WALK
14 - 429
SINGAPORE 5402

Reference : TP 1262/11/20
Vehicle No : SMT 4428P
Make/Model : HONDA SHUTTLE
Insurance Co. : NTUC

RE : QUOTATION FOR REPAIRS TO SMT 4428P FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>AMT \$</u>
1) FRONT BUMPER	1	\$ 1,250.15 <i>dev</i> 925.70
2) FRONT BUMPER RETAINER RH	1	\$ 35.40 <i>? XNN</i>
3) FRONT FENDER RH	1	\$ 485.80 <i>bt</i> 468.20
4) FRONT FENDER COWLING	1	\$ 120.50 <i>de</i>
5) WING MIRROR ASSY RH	1	\$ 547.55 <i>cut</i>
6) FRONT RIGHT DOOR	1	\$ 1,350.10 <i>dd</i> 958.20
7) DOOR TAPE SET	1	\$ 45.80 <i>de</i>
8) TYRE RIM	2	\$ 980.30 <i>dd</i>
9) STEERING RACK & PINON	1	\$ 1,748.80 <i>X NN</i>
LIST PRICE TOTAL		\$ 6,564.40 4046.25
LESS DISCOUNT 20%		\$ 1,312.88 3237
LIST PRICE TOTAL AFTER LESS		\$ 5,251.52

NETT PRICE TOTAL **\$0.00**

TOTAL PARTS COST **\$5,251.52**

LABOUR AND MISCELLANEOUS CHARGES

1) TO REMOVE & REPLACE FRONT BUMPER, FENDER RH, FRONT RH DOOR & PANEL BEAT & ALIGN	\$ 1,000.00	<i>600</i>
	(5 DAYS)	
2) TO PUTTY & SPRAY PAINT FRONT BUMPER, FENDER FRONT RH DOOR, WINGMIRROR, AND OTHER AFFECTED AREA	\$ 800.00	<i>700</i>
	(4 PANEL)	
3) TO TRANSFER FRONT RH DOOR MECHANISM PARTS & GLASS TO NEW DOOR	\$ 150.00	<i>60</i>
4) TO REMOVE & REPLACE STEERING RACK & PINON	\$ 280.00	<i>XNN 150? plus</i>
5) TO REPLACE TYRE RIM & TYRE BALANCING	\$ 80.00	<i>50</i>

6)	COMPUTERISE WHEEL ALIGNMENT	\$	120.00 ⁸⁰	
7)	TUFF KOTE	\$	160.00 ³⁰	
	LABOUR TOTAL	\$	2,590.00	1520
	TOTAL ESTIMATED REPAIR COST	\$	7,841.52	

9254.18

Taufik 97495749/67418437
 WP 19/11/20 @ 1130
 Taufik @ lkkauto.com
 Lumpsum
 Resurvey after repair
 4 to 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: