



38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2011-175
DATE : 17-Nov-2020
POLICY NO. : Direct Asia MT/00712994/01
VEHICLE REG. NO. : SLS26775
VEHICLE MAKE : Toyota Wish 1.8A

FOR SURVEYOR

TO Motor Claim Department
Liberty Insurance Motor Claim
51 Club St, Singapore 069428
Tell : 6221 8611 Fax: 6224 1047 / 6225 6890

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper	1	\$ 680.00	\$ 680.00
2	Front Bumper Clips	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer LH	1	\$ 80.00	\$ 80.00
4	Front Bumper Retainer RH	1	\$ 80.00	\$ 80.00
5	Front Bumper Lower Grille	1	\$ 65.00	\$ 65.00
7	Front Reinforcement	1	\$ 380.00	\$ 380.00
9	Front Sponge	1	\$ 120.00	\$ 120.00
12	Front Head Lamp RH	1	\$ 1,250.00	\$ 1,250.00
14	Front Foglamp Garnish RH	1	\$ 75.00	\$ 75.00
18	Front Fender RH	1	\$ 480.00	\$ 480.00
20	Front Fender Shield RH	1	\$ 150.00	\$ 150.00
21	Front Fender Clips	10	\$ 5.00	\$ 50.00
Total Spare Parts				\$ 3,460.00
	<u>SPECIAL NETT</u>			
22				
Total Special Nett				\$ -
	<u>LABOUR</u>			
23	Spray Painting (Front Bumper And Front Fender RH)	1	\$ 500.00	\$ 500.00
24	Remove, Refit and Repair Affected Accident Parts	1	\$ 600.00	\$ 600.00
26	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,130.00
Amount Before Excess				\$ 4,590.00
Add GST @ 7%				321.30
Total Amount Payable				\$ 4,911.30

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.