

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

18 NOV 2020

E S T I M A T E

Estimate No. : b1 56597	Page No. : 1 of 5
Date Estimated : 18/11/2020	
Prepared By : Foong Shiuh Jye	

- ESTIMATE REPAIR FOR - Tan Ah Yiong 17 guan soon ave Singapore 489594	- ACCOUNT - 158 Lonpac Insurance Bhd 300 Beach Road #17-04/07 The Concourse Singapore 199555
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT6667Z	WBAJB32000G459840	31/03/2017	540ia	0

DESCRIPTION	VALUE
To replace bumper front cover, front left side panel, and front lower spoiler	1700 2,975.00
To spray paint bumper front cover and front left side panel	1730 1,928.00
To replace left headlight and reprogramming.	408 481.00
To remove old PDC assembly, re place damaged parts and reconnect to new bumper including re connet to new bumper and conduct check for proper function.	150 177.00
To check electrical wiring system at the front section for proper function including adjustment of headlights.	150 177.00
Sundries	? 150.00
To supply and install ceramic coating / paint sealant. (By owner).	price? 0.01
Front bumper lower spoiler (by owner)	price / 0.01

Total Labour 1: **5,883.02**

DESCRIPTION	QTY	PRIC	VALUE
FRT LH SIDE PANEL ALUMINIUM <i>for Repair</i>	1	933.30	933.30
LH FOG LAMP SUPPORT (M) ?	1	65.00	65.00
FRT BUMPER PANEL PRIMED (M) <i>cm</i>	1	1,653.55	1,653.55
SET MOUNTING PDC/PMA SENSOR FRT <i>neu</i>	1	69.35	69.35
TRIM GRILLE FRT (I CAM) ?	1	25.45	25.45
FRT LH WHEEL ARCH FRT SECTION COVER ?	1	132.70	132.70
LH BOTTOM COVER ?	1	75.60	75.60
LH HEADLIGHT LED AHL HIGH (ICON LIG <i>cm</i>)	1	4,879.55	4,879.55
Total Parts :			7,834.50

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 56597
Date Estimated : 18/11/2020
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT6667Z	WBAJB32000G459840	31/03/2017	540iA	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 25/11/2020 @ 1345 Excess S\$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 90010088 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 4-5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Labour 1	:	5,883.02
Parts	:	7,834.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	960.23
Grand Total	:	<u>14,677.75</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **