

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

18 NOV 2020

ESTIMATE

Estimate No. : b1 56597
Date Estimated : 18/11/2020
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tan Ah Yiong
17 guan soon ave

Singapore 489594

- ACCOUNT - 158

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT6667Z	WBAJB32000G459840	31/03/2017	540iA	0

DESCRIPTION	VALUE
To replace bumper front cover, front left-side panel, and front lower spoiler	1700 2,975.00
To spray paint bumper front cover and front left side panel	1730 1,923.00
To replace left headlight and reprogramming.	408 481.00
To remove old PDC assembly, re place damaged parts and reconnect to new bumper including re connet to new bumper and conduct check for proper function.	150 177.00
To check electrical wiring system at the front section for proper function including adjustment of headlights.	150 177.00
Sundries	? 150.00
To supply and install ceramic coating / paint sealant (By owner).	price 0.01
Front bumper lower spoiler (by owner)	price 0.01

Total Labour 1: 5,883.02

DESCRIPTION	QTY	PRIC	VALUE
FRT LH SIDE PANEL ALUMINIUM <i>for Repair</i>	1	933.30	933.30
LH FOG LAMP SUPPORT (M) <i>? cm</i>	1	65.00	65.00
FRT BUMPER PANEL PRIMED (M) <i>cm</i>	1	1,653.55	1,653.55
SET MOUNTING PDC/PMA SENSOR FRT <i>reconn</i>	1	69.35	69.35
TRIM GRILLE FRT (I CAM) <i>? x500</i>	1	25.45	25.45
FRT LH WHEEL ARCH FRT SECTION COVER <i>? x500</i>	1	132.70	132.70
LH BOTTOM COVER <i>? x500</i>	1	75.60	75.60
LH HEADLIGHT LED AHL HIGH (ICON LIG) <i>cm</i>	1	4,879.55	4,879.55

Total Parts : 7,834.50

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 2 of 5

Estimate No. : b1 56597
Date Estimated : 18/11/2020
Prepared By : Foong Shiuh Jye

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT6667Z	WBAJB32000G459840	31/03/2017	540iA	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 25/11/2020 @ 1345 Excess S\$ _____

Surveyor's Name RASHU Sign _____

Surveyor's Tel 90010068 Authorised Yes/No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes/No Yes/No

Surveyor's E-mail _____

No. of Working Days Recommend 4-5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Labour 1	:	5,883.00
Parts	:	7,834.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	960.20
Grand Total	:	14,677.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 56597**
Date Estimated : **18/11/2020**
Prepared By : **Foong Shih Jye**

- ESTIMATE REPAIR FOR -
Tan Ah Yiong
17 guan soon ave

Singapore 489594

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT6667Z	WBAJB32000G459E	31/03/2017	540iA	0

DESCRIPTION	ORIGINAL PRICE	NETT
-------------	----------------	------

DESCRIPTION	UNIT PRICE	QTY	NETT
# HEX BOLT nec	1.50	4.00	6.00
# LH BUMPER GUIDE cra	16.95	1.00	16.95
# EXPANDING RIVET D=8MM nec	1.10	4.00	4.40

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	27.35
Total Labour & Parts :	27.35
Deduction for Excess :	
Total Repair Costs less Excess:	27.35
GST @7%:	1.91
Grand Total :	29.26

SGC AUTOGRAPHICS & SIGNS

BLOCK 3015 UBI ROAD 1, #01-268/270 SINGAPORE 408704
Tel: 90196868, 67480982 E-MAIL: sgcstickers@gmail.com
ROC NO: 53233865X

BILL TO:
CASH

INVOICE

INVOICE NO: STK20IN0159
DATE: 07/12/2020

PAYMENT TERMS: C.O.D.

CASH / CHEQUE / BANK TRANSFER ONLY

TEL:
FAX:
ATTN: MARK TAN 8282 6667 (mark.tan@vismark.com.sg)

<u>QTY</u>	<u>DESCRIPTIONS</u>	<u>UNIT PRICE</u>	<u>TOTAL PRICE</u>
1	JOB TO PROVIDE LABOUR, TOOLS AND MATERIALS TO INSTALL PAINT PROTECTION FILM ON THE LEFT HEADLIGHT OF BMW G30 AT OUR WORKSHOP	S 150.00	S 150.00

VEH NO : SGT 6667Z

PAID

BY: Pet S

GRAND TOTAL: \$ 150.00

REMARKS:
CHEQUES SHOULD BE CROSSED AND MADE PAYABLE TO SGC AUTOGRAPHICS & SIGNS

BANK DETAILS:
Bank: OCBC BANK (7339)
Branch: Ubi (588)
Account No.: (588) - 119750 - 001
Beneficiary: SGC Autographics & Signs
Swift Code: OCBCSGSG
PAYNOW : 53233865X



*THIS IS A COMPUTER-GENERATED INVOICE. NO SIGNATURE IS REQUIRED.

Aestheticar Pte Ltd

201400645K

Block 3007, #01-434 Ubi Road 1
Singapore 408701

Receipt after

Bill To #
Mark Tan

Tel : 82826667

INVOICE

No. : INV003010
Date : 21/11/2020
P/O Ref. :
Terms : C.O.D.
Page : 1

o. Code	Description	Qty	Price	Amount
1 001	Coating-BMW G30 540i SGT 6667Z Whole Front Bumper &Left Side Bumper	1	300.00	300.00

SINGAPORE DOLLAR THREE HUNDRED ONLY

Payment made is non refundable and non transferable.

Subtotal	300.00
Discount	0.00
Nett	300.00
Tax	0.00
Grand Total	S\$ 300.00



FOR AESTHETICAR PTE LTD

CUSTOMER SIGNATURE & STAMP

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 56597**
Date Estimated : **18/11/2020**
Prepared By : **Foong Shiuh Jye**

- ESTIMATE REPAIR FOR -
Tan Ah Yiong
17 guan soon ave

Singapore 489594

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT6667Z	WBAJB32000G4598	31/03/2017	540iA	0

DESCRIPTION	ORIGINAL PRICE	NETT
To replace front bumper including make good the front left side panel, align accident area and knock out dented area caused by the accident.	1,700.00	1,700.00 ✓
To respray front bumper and front left side panel.	1,730.00	1,730.00 ✓
To replace left LED AHL headlight and reprogramming.	408.00	408.00 ✓
To remove old PDC assembly parts and reconnect to new bumper including conduct check for proper function.	150.00	150.00 ✓
To check electrical wiring system at the front section for proper function.	150.00	150.00 ✓
Sundries	150.00	150.00 ✓
To supply and install protection film on left headlight. (By owner).	150.00	150.00
To install front lip labour. (By owner).	100.00	100.00
To supply coating on front bumper and front left side fender. (By owner).	300.00	300.00

DESCRIPTION	UNIT PRICE	QTY	NETT
# HEX BOLT	1.50	4.00	6.00 ✓
# LH BUMPER GUIDE	16.95	1.00	16.95 ✓
LH FOG LAMP SUPPORT (M)	65.00	1.00	65.00 ✓
FRT BUMPER PANEL PRIMED (M)	1,653.55	1.00	1,653.55 ✓
# EXPANDING RIVET D=8MM	1.10	4.00	4.40 ✓
LH HEADLIGHT LED AHL HIGH (ICON LIG	4,879.55	1.00	4,879.55 ✓

SUPPLEMENTARY ITEMS

Total Labour :	4,838.00
Total Parts :	6,625.45
Total Labour & Parts :	11,463.45
Deduction for Excess :	0.00
Total Repair Costs less Excess:	11,463.45
GST @7%:	802.44
Grand Total :	12,265.89