

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO/GST Reg. No. 201019626G

SHC5779T**AAD2011-089***Not Notarised*
11 Sep 2020

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

17 NOV 2020**SHC5779T**

VF1ABL15AUC281634

RENAULT

LATITUDE

14/11/2020

FCI

10/7/2015

	PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Re</i> 561.70	✓
2	1 BUMPER LOWER REAR	\$	<i>Re</i> 411.90	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Re</i> 98.10	X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Re</i> 82.10	X
5	1 BUMPER RETAINER RH REAR	\$	<i>Re</i> 59.80	X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Re</i> 80.80	X
8	1 BUMPER RETAINER LH REAR	\$	<i>Re</i> 54.20	X
10	1 BUMPER BEAM REAR	\$	<i>Re</i> 547.80	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Re</i> 114.50	} X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Re</i> 114.50	
13	1 OUTER PANEL REAR (End Panel)	\$	<i>Re</i> 745.80	
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Re</i> 404.56	
15	1 BOOT REAR	\$	<i>Re</i> 1,677.20	
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Re</i> 277.70	
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Re</i> 277.70	
18	1 BOOT HINGE LH	\$	<i>Re</i> 254.20	
19	1 BOOT HINGE RH	\$	<i>Re</i> 254.20	
20	1 BOOT LOCK	\$	<i>Re</i> 246.60	
21	1 BOOT LOCK CATCH	\$	<i>Re</i> 41.70	
22	1 BOOT FINISHER	\$	<i>Re</i> 344.70	
23	1 BOOT BADGE 'RENAULT'	\$	<i>Re</i> 82.40	
24	1 BOOT BADGE	\$	<i>Re</i> 95.80	
25	1 BOOT FINISHER	\$	<i>Re</i> 344.70	
26	1 TAILLAMP RH	\$	<i>Re</i> 401.40	
27	1 TAILLAMP LH	\$	<i>Re</i> 401.40	
		\$	7,975.46	
		10% \$	797.55	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHCS779T

AAD2011-089

\$	7,177.91
----	----------

Special Nett

1 1SET PARKING AID	\$	700.00	X
2 1 BOOT FINISHER NUT L70Y	\$	60.00	X
3 1SET REAR BUMPER CLIP	\$	66.00	✓
4 1SET BUMPER BRACKET CTR CLIP	\$	33.00	X
5 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
6 1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
7 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
8 1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
9 1SET BUMPER LOWER REAR RIVET	\$	22.00	X
10 1SET BUMPER LOWER REAR CLIP	\$	66.00	✓
11 1 EXHAUST MOUNTING REAR	\$	17.82	X
12 1 REAR NUMBER PLATE WITH HOLDER	\$	120.00	X
13 1 REAR BOOT STICKER 'Trans-cab'	\$	80.00	X
14 1 REAR BOOT STICKER '6555-3333'	\$	80.00	X
TOTAL	\$	1,304.82	
TOTAL PARTS	\$	8,482.73	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	220/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	200/
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	60/
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5779T**AAD2011-089**

To check steering geometry and computer wheel alignment \$ *nn* 220.00 *X*

To Check Electrical Lighting Concerned. \$ 170.00 *10/*

TOTAL \$ 7,070.00

Over All Total \$ 22,730.65

(LUMP SUM)

Repair Days

*20 DAYS**2 day***For Official Use**

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: