

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: ~~CHINA TAIPING INSURANCE~~ ^{MSIG} (SINGAPORE) PTE. LTD.
Att: Motor Claims Dept

ACCIDENT INVOLVING SLM3083E [YOUR INSURED] & GV4098T [OUR CLIENT]
ON 18/11/2020.

ESTIMATED REPAIR COSTS FOR GV4098T

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	FRONT PANEL <i>Dented</i>	<i>873.00</i>	\$ 1,139.26 ✓
1PC	FRONT GRILLE <i>Crack</i>	<i>568.00</i>	\$ 632.24 ✓
1PC	FRONT GRILLE MITSUBISHI EMBLEM <i>NH</i>		\$ 128.75 X
2PCS	HEAD LAMP LH / RH @ \$655.02 EACH <i>Crack / broken 584.84 x 2</i>		\$ 1,310.04 ✓
2PCS	SIGNAL LAMP LH / RH @ \$214.34 EACH <i>NH</i>	<i>1169.68</i>	\$ 428.68 X
2PCS	SIDE LAMP LH / RH @ \$178.75 EACH <i>NH</i>		\$ 357.50 X
1PC	FRONT BUMPER <i>dented</i>	<i>444.40</i>	\$ 498.25 ✓
1PC	FRONT BUMPER BRACKET <i>o/s w/t</i>		\$ 129.05 ✓
2PCS	TAIL LAMP LH / RH @ \$249.86 EACH <i>o/s crack w/s NH</i>		\$ 499.72 ✓
1PC	REAR NO. PLATE LAMP <i>NH</i>		\$ 63.05 X
1PC	SPARE TYRE BRACKET <i>NH</i>		\$ 469.23 X
1PC	SPARE TYRE HOLDER <i>NH</i>		\$ 25.15 X

3433.99

3090.59

PARTS SUM: \$ 5,680.92
PARTS LESS ~~25%~~: \$ 1,420.23 *10%*
PARTS TOTAL: \$ 4,260.69

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY FRONT GRILLE CLIPS <i>NH</i>	\$ 50.00 <i>20/-</i>
*	TO SUPPLY FRONT PANEL SEALANT <i>NH</i>	\$ 80.00 X
*	TO SUPPLY 2PCS TAILGATE @ \$2,600 EACH <i>NH</i>	\$ 3,200.00 X
*	TO SUPPLY REAR END PANEL <i>NH</i>	\$ 1,500.00 X
*	TO SUPPLY REAR END PANEL SEALANT <i>NH</i>	\$ 80.00 X
*	TO SUPPLY REAR NO. PLATE <i>W/T</i>	\$ 100.00 <i>20/-</i>
*	TO SUPPLY 4PCS TAILGATE HINGE <i>NH</i>	\$ 1,000.00 X
*	TO SUPPLY 2PCS TAILGATE LOCK <i>NH</i>	\$ 800.00 X
*	TO SUPPLY 2PCS TAILGATE CATCH <i>NH</i>	\$ 600.00 X

40.00

*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00	HH
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	\$ 1,600.00 500/-	
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	\$ 1,600.00 200/-	
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	\$ 1,600.00 100/-	
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	\$ 1,600.00 HH	
*	TO TUFF COAT DAMAGED AREAS	860.00	\$ 300.00 30/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 30/-	
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	HH

LABOUR & S/N TOTAL: \$ 14,910.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 19,170.69

19/11/2020 @ 1100am

Not Actual

Lbment 4 days.

Ryan

LKK Auto



Check MV

Check part prices.

3990.59

L/S 3,000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: