

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Place # 05-01/ 06
 Singapore Land Tower
 Singapore 048623
 Tel : 64 6329 - 5324
 Fax : 6221 - 3147

Quotation

DATE : 19.11.2020
 VEH NO : SJJ2349K
 MODEL : Honda Civic
 D O A : 18.11.2020
 YR REF : XB8356B

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJJ2349K (HONDA CIVIC)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Debond</i>	1	638.00 ✓
2	Rear Bumper Side Holder - LH & RH <i>new</i>	2	46.80 ✓
3	Rear Bumper Exhaust Garnish <i>new</i>	1	25.30 +
4	Rear End Panel <i>Dented</i>	1	360.50 ✓
5	Rear End Panel Top Garnish <i>Debond</i>	1	78.60 ✓
6	Tail Lamp - LH & RH <i>cracked</i>	2	492.20 ✓
7	Tail Lamp Lower Bracket - LH & RH <i>Bent</i>	2	21.00 ✓
8	Tail Lamp Panel - LH & RH <i>LH Buckled</i>	2	182.60 <i>91.30</i>
9	Bootlid <i>Distorted</i>	1	693.80 ✓
10	Bootlid Lock <i>Damaged</i>	1	121.40 ✓
11	Bootlid Weatherstripe <i>cut</i>	1	114.90 ✓
12	Bootlid Number Plate Lamp <i>new</i>	2	106.00 +
13	Bootlid Number Plate Lamp Garnish <i>cracked</i>	1	110.10 ✓
14	Bootlid Reflector - LH & RH <i>cracked</i>	2	390.00 ✓
15	Bootlid Hinges <i>Bent</i>	2	160.80 ✓
16	Bootlid Hinges Cover <i>new</i>	2	184.60 +
17	Bootlid Inner Trim Board <i>Debond</i>	1	185.90 ✓
18	Honda Logo <i>new</i>	1	36.90 ✓
19	Civic Emblem <i>new</i>	1	34.60 ✓
20	1.8 Emblem <i>new</i>	1	23.70 ✓
21	i-vect Emblem <i>new</i>	1	40.50 ✓
22	Rear Fender - LH <i>Buckled</i>	1	941.50 ✓
23	Rear Fender Inner Trim Board <i>LH Debond</i>	2	480.80 <i>240.40</i>
24	Spare Tyre Panel Top Cover <i>Debond</i>	1	303.80 ✓
25	Rear Exhaust Pipe <i>new</i>	1	514.20 +
26	Rear Exhaust Mounting <i>new</i>	1	36.00 +
27	Rear Windscreen Moulding <i>new</i>	1	121.00 ✓

5247.70
4198.16

Less 20%

\$	6,445.50
	(1,289.10)
\$	5,156.40

S/NET ITEMS

1	Rear Bumper Clips <i>new</i>	1 set	30.00	✓
2	Reverse Sensor <i>changed</i>	1	280.00	200.
3	Rear End Panel Top Garnish Clips <i>new</i>	1 set	20.00	✓
4	Rear End Panel Sealant <i>new</i>	1 set	60.00	✓
5	Tail Lamp Sponge Gasket <i>new</i>	2	40.00	✓
6	Bootlid Number Plate Lamp Garnish Clips <i>new</i>	1 set	20.00	✓
7	Bootlid Reflector Sponge Gasket <i>new</i>	2	40.00	✓
8	Bootlid Hinge Cover Clips <i>new</i>	1 set	50.00	+
9	Bootlid Inner Trim Board Clips <i>new</i>	1 set	30.00	✓
10	Rear Fender Inner Trim Board Clips <i>new</i>	1 set	60.00	30
11	Rear Exhaust Tail Pipe <i>new</i>	2	240.00	+
12	Rear Windscreen Sealant <i>new</i>	1	60.00	530 ✓
13	Rear Number Plate	1	30.00	+
14	Rear Number Plate Holder <i>new</i>	1	30.00	+

\$ 990.00

Total parts

\$ 6,146.40

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,600.00	1300.
2	To putty & spray up paint works	\$	1,600.00	1200.
3	To check wiring system	\$	50.00	30
4	To spray tuff coat	\$	180.00	120.
5	To remove reverse sensor	\$	100.00	50
6	To remove upholstery	\$	150.00	80
7	To transfer bootlid fittings	\$	150.00	60.
8	To remove fuel tank	\$	150.00	80.
9	To remove rear windscreen	\$	180.00	120
10	To remove exhaust pipe	\$	150.00	X
		\$	4,310.00	

Grand Total

\$ 10,456.40

GST Will be reflected in the final bills

NOTE : -

**PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.**

total: 7768.16.

L/S: 6.2K.

09 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: