



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 1783X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	1,288.20	-
1	REAR N/S BOOT LID REFLECTOR	SERVICEABLE	305.10	-
1	REAR BOOT LID EMBLEM "LOGO"	NECESSARY	35.20	35.20
1	REAR TAIL-GATE EMBLEM "ELANTRA"	NECESSARY	35.10	35.10
1	REAR BOOT LID EMBLEM "ELITE"	NECESSARY	30.70	30.70
1	REAR BOOT RUBBER	SERVICEABLE	155.20	-
1	REAR N/S TAIL-LAMP ASSY	CRACKED	876.20	876.20
1	REAR END PANEL	TO REPAIR SEE LABOUR	435.60	-
1	REAR END PANEL SENSOR	DENTED	135.60	135.60
1	REAR N/S FENDER INNER TRIM	SERVICEABLE	255.70	-
1	REAR BUMPER	BUCKLED	495.10	495.10
1	REAR BUMPER LOWER GARNISH	DENTED / CUT	295.60	295.60
1	REAR BUMPER REINFORCEMENT	CRACKED	353.60	353.60
1	REAR N/S BUMPER REFLECTOR	CRACKED	85.70	85.70
1	REAR N/S BUMPER SIDE RETAINER	SERVICEABLE	65.10	-
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	793.40	-
	LESS 20% DISCOUNT		-1,128.22	-468.56
			4,512.88	1,874.24
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR REVERSE SENSOR (SN)	SHORTED	200.00	200.00
20	BUMPER CLIP @\$2.00 (SN)	NECESSARY	40.00	40.00
			240.00	240.00
<u>LABOUR</u>				
	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF REAR BOOT LID, REAR END PANEL AND REAR EXHAUST SILENCER.		800.00	300.00
	PUTTY & SPRAY PAINT ON REAR ACCIDENT AFFECTED PORTION.		1,000.00	600.00
	CHECK / RECONNECT WIRING.		45.00	20.00

Report Ref No. CS/FCI20012734/Ksd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION.	NOT NECESSARY	150.00	-
	REMOVE / REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	REMOVE / RENEW EXHAUST SILENCER.	NOT NECESSARY	120.00	-
			2,235.00	920.00
GRAND TOTAL			6,987.88	3,034.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CS/FCI20012734/Ksd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.