



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI20012734/Ksd3e2	
			Date: 21/12/2020	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 3260X	Veh. Inspected	SKV 1783X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D20004719MFSH	Excess (\$)	0.00	
Assign From	SANGHILAN VIC	Assign Date	19/11/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHDH41CMGU626028	Colour	METALLIC PEARL WHITE	
Odometer	207909 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40Z R18	MICHELIN	7 mm	
L/H Front Tyre	225/40Z R18	MICHELIN	7 mm	
R/H Rear Tyre	225/40Z R18	MICHELIN	7 mm	
L/H Rear Tyre	225/40Z R18	MICHELIN	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/11/2020	Inspection Date	18/11/2020	
Survey held at	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PK 2			
Repairer	MASSIVE TRADING & AUTO			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	