



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 12/11/2020

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB8035H
Case Reference Number	BUS/11/20/7006
Registration Date	5/10/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NG 363F (A24)
Name of Driver	S. Govindharaj A/L Shanmugam
Type of Accident	Head to Rear
Accident Date and Time	6/11/2020 11:37 AM
Accident Reported Date and Time	6/11/2020 1:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB8035H-REAR PORTION GBC1458S (TP) INSURED WITH NTUC
Prepared Date and Time	12/11/2020 9:58 AM
Chassis Number	WMAA24Z20F7002745
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,650.00	\$0.00
Total Spray Cost	\$528.00	\$0.00
Total Spare Part Cost	\$7,551.61	\$0.00
Total Other Cost	\$300.00	\$0.00
TOTAL COST	\$11,029.61	\$0.00
Lump Sum Total	\$11,050.00	\$0.00
Number of Repair Days	6.0	
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	12/11/2020 10:19 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/11/2020

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,650.00	2120
Total Labour	\$2,650.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$528.00	446
Total Spray Painting & Panel Beating	\$528.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$300.00	X
Total Other Costs	\$300.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			REFLECTOR STICKER BUMPER	1.00	\$75.00	0.00	\$75.00	Replace	1/NEC
6011407	Body		DOOR,ENGINE:REAR,MAN A22 'C' SERIES	1.00	\$1,625.00	10.00	\$1,462.50	Replace	1/CRY
6011408	Body		BUMPER:REAR,CENTR E,MAN A22 'C' SERIES	1.00	\$1,625.00	10.00	\$1,462.50	Replace	1/CRY
6010298			LAMP,STOP:LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	1/CRA
6010299			SIGNAL LAMP LED	1.00	\$1,274.10	10.00	\$1,146.69	Replace	1/CRY
6010062	Body	F01001-CW273	COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	1/CRY
6010463	Body	S01001-CW006	FRAME,REAR BUMPER:FOR MAN A22 BUS	1.00	\$1,423.20	10.00	\$1,280.88	Replace	1/CRY X R
6010372	Body	4001F09-ACCE5021	PANEL,REFLECTOR:REAR,LH,FOR MAN BUS	1.00	\$107.00	10.00	\$96.30	Replace	1/CRY NEC
6010373	Body	4001F09-ACCE5020	PANEL,REFLECTOR:REAR,RH,FOR MAN BUS	1.00	\$107.00	10.00	\$96.30	Replace	1/CRA
6010412	Body	4001G01-GSP438	SPRING,GAS:500N,FOR MAN NL320F (A22)	1.00	\$241.50	10.00	\$217.35	Replace	1/BT
6009375	VM		RETAINER,MALE & FEMALE,REAR LID,MAN BUS	2.00	\$74.80	10.00	\$134.64	Replace	1/X SVC.
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	1/NEC
			STICKER 60KM/H	1.00	\$5.00	0.00	\$5.00	Replace	1/NEC
6010295	Body	S06006-CW556	DOOR,ENGINE:REAR FRAME,FOR MAN A22 BUS	1.00	\$1,207.50	10.00	\$1,086.75	Replace	1/CRY X R
6010300	VE	36-25103-6000	LAMP,REVERSE (MAN BUS)	1.00	\$77.60	10.00	\$69.84	Replace	1/CRY X R
6010323	Body	4000F06-HING735	HINGE:RH,REAR ENGINE DOOR,FOR MAN A22	1.00	\$138.00	10.00	\$124.20	Replace	X R
6010322	Body	4000F06-HING734	HINGE:LH,REAR ENGINE DOOR,FOR MAN A22	1.00	\$138.00	10.00	\$124.20	Replace	X R
6010371	Body	88-25215-0001	REFLECTOR,TRIM:FOR MAN BUS	1.00	\$77.60	0.00	\$77.60		1/SCR.
Total					\$10,387.70		\$9,439.51		

Added Spare Parts / Material Usage After Surveyor Signed off

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair dy - 5 days.

L/S.

After pump photo

Sum Pn (4416)

12/11/2020



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/11/2020

User ID : GohKK2

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									