

Main Office:
 Mová Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

18/11/2020

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SLC7298D

Veh Model :- PEUGEOT 308 1.2

Estimate# :- CK421223

Claim # :-

ACC. Date :- 17/11/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1. REAR BOOT
2. REAR BOOT LOGO
3. REAR BOOT EMBLEM 308
4. REAR BOOT EMBLEM "PEUGEOT"
5. REAR BOOT EMBLEM "PURETECH"
6. REAR BOOT EMBLEM
7. REAR BOOT LOCK
8. REAR BOOT CATCH
9. REAR BOOT HINGE L+R
10. REAR BOOT INNER TRIM
11. REAR BOOT INNER TRIM L+R
12. REAR BOOT RUBBER
13. REAR BOOT WIPER ARM
14. REAR BOOT WIPER BLADE
15. REAR BOOT WIPER MOTOR
16. REAR BOOT DAMPLE L+R
17. REAR BOOT LAMP L+R
18. REAR WINDSCREEN GLASS
19. REAR WINDSCREEN MOULDING
20. REAR WINDSCREEN SIDE GARNISH L+R
21. REAR LAMP L+R
22. REAR LAMP CLIPS
23. REAR BUMPER
24. REAR BUMPER TOW COVER
25. REAR BUMPER LOWER GARNISH
26. REAR BUMPER SENSOR
27. REAR BUMPER SENSOR WIRE
28. REAR BUMPER SENSOR BRACKET
29. REAR BUMPER UNDER COVER
30. REAR BUMPER REINFORCEMENT
31. REAR BUMPER BRACKET
32. REAR BUMPER RETAINER
33. REAR PANEL
34. REAR PANEL INNER MEMBER
35. REAR PANEL INNER TRIM
36. REAR PANEL INNER TRIM CLIPS
37. REAR FLOOR PANEL - TO REPAIR
38. REAR FLOOR TOP COVER - TO CONFIRM
39. REAR FENDER INNER TRIM L+R - TO CONFIRM

12547.00
 Supplementary 333.00
 12880.00
 -10% 1288.00
 11592.00
 S/Nett 390.00
 L.R 2110.00
 \$14092.00
 LS\$11250/-

1	PC	2,538.00	2,538.00	✓
1	PC	86.00	86.00	✓
1	PC	84.00	84.00	✓
1	PC	89.00	89.00	✓
1	PC	65.00	65.00	✓
1	PC	25.00	25.00	✓
1	PC	335.00	335.00	✓
1	PC	108.00	108.00	✓
2	PC	138.00	276.00	✓
1	PC	632.00	632.00	✓
2	PC	110.00	220.00	✓
1	PC	198.00	198.00	✓
1	PC	65.00	65.00	✓
1	PC	44.00	44.00	✓
1	PC	756.00	756.00	✓
2	PC	142.00	284.00	✓
2	PC	212.00	424.00	✓
1	PC	1,256.00	1,256.00	✓
1	PC	26.00	26.00	✓
2	PC	144.00	288.00	✓
2	PC	298.00	596.00	✓
2	PC	18.00	36.00	✓
1	PC	1,375.00	1,375.00	✓
1	PC	55.00	55.00	✓
1	PC	323.00	323.00	✓
4	PC	279.00	1,116.00	✓
1	PC	481.00	481.00	✓
1	SET	165.00	165.00	✓
1	PC	105.00	105.00	✓
1	PC	398.00	398.00	✓
1	SET	98.00	98.00	✓
1	SET	88.00	88.00	✓
1	PC	656.00	656.00	✓
1	PC	368.00	368.00	✓
1	PC	216.00	216.00	✓
6	PC	12.00	72.00	✓
1	PC			
1	PC			
2	PC			

LIST TOTAL S\$

10% DISCOUNT S\$

+ Boot Stopper Ltr @ \$28.00 X 2
 + Keyless Sensor \$277.00

13,947.00

-1,394.70

12,552.30

SPECIAL NET ITEMS :

1. REAR WINDSCREEN SEALANT
2. REAR WINDSCREEN FILMING
3. REAR NUMBER PLATE

1	PC	80.00	80.00	✓
1	PC	250.00	250.00	✓
1	PC	60.00	60.00	✓

\$390/-

Estimate

18/11/2020

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 139526
Veh # :- SLC7298D
Veh Model :- PEUGEOT 308 1.2
Estimate# :- CK421223
Claim # :-
ACC. Date :- 17/11/20
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg
Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	SPECIAL NET TOTAL S\$			390.00
	LABOUR :			
	TO CUT & WELD RERA END PANEL, TO REPAIR REAR FLOOR PANEL, REAR FENDER L+R, REAR CHASSIS MEMBER L+R. TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS		800	1,140.00
	TO SPRAY AFFECTED AREAS		900	1,000.00
	TO REMOVE & REFIX REAR WINDSCREEN GLASS		120	180.00
	TO REMOVE & REFIX REAR BOOT MECHANISM, CHECK & TEST POWER LOCK & WIPER MOTOR		60	80.00
	TO REMOVE & REFIX REAR LAGGAGE COMPARTMENT SIDE COVER, SIDE TRIM BOARD, CARPET & OTHER ATTACHMENT PARTS		60	100.00
	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE		30	60.00
	TO RUST PROOF AFFECTED AREAS		40	80.00
	TO RESET REAR BOOT FOR FUNCTION		200	200.00
	LABOUR TOTAL S\$		2110	2,840.00

Tanpin 97493449
up 19/11/20 @ 12pm
** check repair limit*
check 4/5 for p/p repair
** Reserving check items, before/after print.*
Keong

NON-TAX AMOUNT S
AMOUNT S\$ 15,782.30
GST @ 7 % 1,104.76
AMOUNT DUE S\$ 16,887.06

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Tanpin C / Khantowin

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : **(65) 6476 3333**
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : **(65) 6272 3892**
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

SUPPLEMENTARY

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Page : 1
Veh No : SLC7298D
Model : PEUGEOT 308
Acc Date : 17-Nov-20
Incharge : KEONG

No	Description	Qty	U.Price	Amt \$
LIST ITEMS				
1	BOOT STOPPER L+R	2	\$ 28.00	\$56.00
2	KEY LESS SENSOR	1	\$ 277.00	\$277.00
LIST TOTAL S\$				<u>\$333.00</u>
10% DISCOUNT				<u>\$33.30</u>
				<u><u>\$299.70</u></u>

NON-TAX AMOUNTS	\$299.70
GST @ 7%	\$20.98
AMOUNT DUE	<u><u>\$320.68</u></u>



Customer's Signature/Co.Stamp

MOVA AUTOMOTIVE PTE LTD