

ESTIMATE TO REPAIR

VEHICLE NO. : SDU 9933 R
MAKE : HONDA
MODEL : CIVIC
YEAR : 17/01/2019
CHASSIS NO : MRHFC5650JT002116

SURVEYOR NAME : LKK KENNETH
DATE OF SURVEY : 23/11/20
TIME OF SURVEY :

DATE : 18 November 2020
DATE OF ACCIDENT : 17 November 2020
THIRD PARTY REF : SMT 9144 A
THIRD PARTY REF : AUTO & GENERAL INSURANCE (S) PL

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper				\$ CM 617.50
2 pcs	rear bumper retainer		\$ 15.00		\$ Sm 30.00
1 pc	rear bumper reinforcement				\$ B 160.00
2 pc	rear bumper sensor		\$ 145.80		\$ Sm 291.60
1 pc	rear bumper lower garnish				\$ 60.30
10 pcs	rear bumper clips		\$ 3.50		\$ 35.00
	Less 20%				\$ 1,194.40
					\$ 238.88
					\$ 955.52
	To check rear wiring & repair sensor				\$ Sol 80.00
	To putty & spray paint				\$ 220 300.00
	Labour charges				\$ 200 250.00
	Not Notified Puttying B4 paint 2 days 1168.24				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
TG/SO	TOTAL				\$ 1,585.52