



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2105901

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 20/08/2021
Reference CC4/LPC20012746/T1es3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMD 497A
Insured Veh. SLR 2236L
Claim No. 20/20/20/VP05/023917
Policy No. Z20VP05025967
Accident Date 22/10/2020
Inspection Date 23/11/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20012746/T1es3q2 Date: 20/08/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLR 2236L	Veh. Inspected	SMD 497A	
Policy No.	Z20VP05025967	Coverage (\$)	0.00	
Claim No.	20/20/20/VP05/023917	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	19/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MR053DK5100113474	Colour	GREY	
Odometer	38945 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MICHELIN	6 mm	
L/H Front Tyre	215/60 R16	MICHELIN	6 mm	
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/10/2020	Inspection Date	23/11/2020	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 497A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	SEALANT (SN)	NECESSARY	200.00	100.00
1	COVER ,RR BUMPER L/C (SN)	DEFORMED	657.60	657.60
1	REAR BPR REINFORCEMENT (SN)	DEFORMED	399.50	399.50
1	PANEL ,LAMP LOWER (SN)	NOT NECESSARY	670.00	-
1	RR FLR CROSS MEMBER 3, (SN)	NOT NECESSARY	168.50	-
1	RETAINER ,RR BUMPER R (SN)	NECESSARY	110.50	110.50
1	RETAINER ,RR BUMPER (SN)	NECESSARY	110.50	110.50
1	PANEL ,LUGGAGE DR (SN)	BENT	1,143.70	1,143.70
1	REAR BOOT LID EMBLEM (SN)	NECESSARY	50.70	50.70
1	PLATE LUGGAGE (SN)	NECESSARY	45.70	45.70
1	PLATE ,LUGGAGE COMPT (SN)	NECESSARY	35.60	35.60
1	PLATE ,LUGGAGE COMPT (SN)	NECESSARY	41.00	41.00
			3,733.30	2,744.80
	<u>LABOUR</u>			
	CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.		180.00	180.00
	RESET AND REPROGRAMME ECU.		180.00	180.00
	DRILL HOLE TO INSTALL REVERSE SENSOR .		180.00	180.00
	REMOVE REAR BOOT COMPONENTS TO TRANSFER ONTO NEW BOOT.		360.00	360.00
	REMOVE REAR BOOT INTERIOR TO ASSIST REPAIR.		360.00	360.00
	LABOUR FOR PLATINUM SHINEPRO & SHINEPER PANEL APPLICATION ON REAR BUMPER AND REAR BOOT .		183.18	183.18
	REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE ,REPAIR ,STRAIGHTEN REAR BUMPER ,REAR BOOT ,TAIL-LAMP ,PANEL AND AFFECTED PORTION OF CAR.		3,600.00	2,160.00
	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.		2,360.00	1,770.00
			7,403.18	5,373.18
	GRAND TOTAL		11,136.48	8,117.98



RECOMMENDED COST OF REPAIRS			8,117.98
-----------------------------	--	--	----------

Report Ref No. CC4/LPC20012746/T1es3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMD 497A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

