



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188
Customer Detail

ESTIMATE

Account Detail	Account No	Dr Yeo Song Huat 687D Choa Chu Kang Drive #20-374 Singapore 684687 Mobile: 93550223
THIRD PARTY CLAIM	S1000020/TPCLAIM	
	Document No	
	Document Date	
	0	
	18/11/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	JETHE	E7	31/07/2018	SMD0497A	0	58181	65/DS/SMD0497A
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

MR053DK5100113474	6ARP424020	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	------------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : <i>longpac hrs.</i> T/P VEH. : SLR2236L ACC DATE : 22.10.20 BY :				50. 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100. 200.00
3	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				✓ 180.00
4	S	BP-SUBLET RESET AND REPROGRAMME ECU.				✓ 180.00
5	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				✓ 360.00
6	B	BP-LAB2 REMOVE REAR BOOT COMPONENTS TO TRANSFER ONTO NEW BOOT.				✓ 360.00
7	B	BP-LAB2 REMOVE REAR BOOT INTERIOR TO ASSIST REPAIR.				✓ 183.18
8	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR BUMPER AND REAR BOOT				

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	<i>Tan Jm 97495749</i> <i>Wp 23/11/2020 1130</i> <i>07 days</i> <i>Resurvey before paint</i> <i>Amount Due tan jm @ lkhankawin</i>
		Labour	
		Materials	
			Amount Due

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

4381557

4381557

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO

SMD0497A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchape

Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462

Tel no.: 6631 1188
Customer Detail

ESTIMATE

Account Detail	Account No	Dr Yeo Song Huat 687D Choa Chu Kang Drive #20-374 Singapore 684687 Mobile: 93550223
THIRD PARTY CLAIM	S1000020 / TPCLAIM	
	Document No	
	Document Date	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	JETEHT E7	ASV51R	31/07/2018	SMD0497A	0	58181	65/DS/SMD0497A
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

MR053DK5100113474	6ARP424020	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	------------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS ⁷²⁰ TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, REAR BOOT, TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR.				2160 3600.00
10	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED ⁵⁹⁰ PORTION OF CAR.				1770 2360.00
11	1	S52159-0X902 COVER, RR BUMPER L/C	1.00	657.60		de 657.60
12	2	S52023-06081 REAR BPR REINFORCEMENT,	1.00	399.50		? 399.50
13	3	S58307-06190 PANEL, LAMP LOWER	1.00	670.00		? 670.00
14	4	S57654-06040 RR FLR CROSS MEMBER 3,	1.00	168.50		? 168.50
15	5	S52575-06131 RETAINER, RR BUMPER R	1.00	110.50		ne 110.50
16	6	S52576-06131 RETAINER, RR BUMPER	1.00	110.50		ne 110.50
17	7	S64401-06820 PANEL, LUGGAGE DR	1.00	1143.70		bt 1143.70
18	8	T90975-02063 REAR BOOT LID EMBLEM,	1.00	50.70		ne 50.70
19	9	S75442-06230 PALTE, LUGGAGE	1.00	45.70		ne 45.70
20	0	S75443-06810 PLATE, LUGGAGE COMPT	1.00	35.60		ne 35.60
21	1	S75443-06B70 PLATE, LUGGAGE COMPT	1.00	41.00		ne 41.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	11,136.48
		Labour 3,433.30	GST 7.00%
		Materials 7,340.00	Less
		Lubrication/Fluid 363.18	0.00
		Others 0.00	0.00
			Amount Due
			11,916.03

PLEASE TEAR ALONG PERFORATED LINE

4381558

TO SECURITY GUARD

4381558

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 18/11/2020
TIME 10:08

VEHICLE NO

SMD0497A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors