



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI19018573/Gtf3e2-1

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 09-12-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 415R	Veh. Inspected	SKP 3560R
Policy No.	DMPCSN30719218000	Coverage (\$)	0.00
Claim No.	SNM19D204878C02	Excess (\$)	0.00
Assign From	ELAINE CHEONG	Assign Date	19/11/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E250	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WDD2120472A482136	Colour	BLACK
Odometer	143617	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/35Z R19	DUNLOP	6 mm
L/H Front Tyre	255/35Z R19	DUNLOP	6 mm
R/H Rear Tyre	255/35Z R19	DUNLOP	6 mm
L/H Rear Tyre	255/35Z R19	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	14/10/2019	Inspection Date	24/11/2020
Survey held at	M-TECH MOTOR SERVICES BLK 9005 TAMPINES STREET 93 #01-252, TAMPINES INDUSTRIAL PARK A SINGAPORE 528839		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------