



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104569

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 30/06/2021
Reference CC4/FCI20012755/Uba3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FBL 2101S
Insured Veh. SHC 7580K
Claim No. D20004699MFSH
Policy No. D-20094921MFSH
Accident Date 14/11/2020
Inspection Date 20/11/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20012755/Uba3q2 Date: 30/06/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7580K	Veh. Inspected	FBL 2101S	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20004699MFSH	Excess (\$)	0.00	
Assign From	ERIC WOO	Assign Date	19/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA (XSR900)	c.c	847	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JYARN431000003743	Colour	SILVER	
Odometer	58768 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70Z R17	MICHELIN	7 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	180/55Z R19	MICHELIN	7 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S & O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/11/2020	Inspection Date	20/11/2020	
Survey held at	AUTO N CARS SERVICES (COMMERCIAL) PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 2101S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH HANDLE GRIP ASSEMBLY (WCP)	NOT NECESSARY	32.00	-
1	RH HANDLE BALANCER (WCP)	SCRATCHED	18.50	18.50
1	RH BRAKE HANDLE (WCP)	CUT	45.80	45.80
1	BRAKE WIREHARNESS (WCP)	TORN	35.50	35.50
1	RH SIDE MIRROR (WCP)	CUT	135.00	135.00
1	RH OUTER ABSORBER FORK (WCP)	TO REPAIR SEE LABOUR	280.00	-
1	RH FRONT FENDER BRACKET (WCP)	TO REPAIR SEE LABOUR	205.00	-
1	RADIATOR SIDE GUIDE (WCP)	TO REPAIR SEE LABOUR	135.00	-
1	RH RADIATOR BOTTOM HOSE (WCP)	NOT NECESSARY	16.50	-
1	RH SIDE GUIDE ASSEMBLY (ENGINE)	CUT	98.00	98.00
1	RH SIDE GUIDE -BLOCK SLIDER ASSEMBLY (WCP)	CUT	165.00	165.00
1	FRONT EXHAUST HEAT SHIELD (WCP)	BENT	120.00	120.00
1	REAR EXHAUST HEAT SHIELD (WCP)	CUT	110.00	110.00
1	FRONT BRAKE PADLE (WCP)	CUT	220.00	160.00
1	RH PASSENGER FOOT REST BRACKET (WCP)	SERVICEABLE	19.50	-
1	GUIDE -STAND ARM BUSH ASSEMBLY (WCP)	NOT NECESSARY	58.00	-
1	BRAKE PADLE GUIDE (WCP)	CUT	210.00	210.00
1	PETROL TANK (WCP)	TO REPAIR SEE LABOUR	367.70	-
1	HANDLE BAR (WCP)	BENT	185.50	185.50
	COST PLUS 15%		368.55	192.50
			2,825.55	1,475.80
	<u>LABOUR</u>			
	LABOUR TO REPLACE HANDLE BAR AND RH OUTER ABSORBER FORK .INCLUSIVE OF THE REPAIR OF RH OUTER ABSORBER FORK,RH FRONT FENDER BRACKET ,RADIATOR SIDE GUIDE AND PETROL TANK .		300.00	200.00
	TOP UP COOLANT & DO PRESSURE TEST.	NOT NECESSARY	80.00	-
	TO REPLACE PETROL TANK .}		80.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT PETROL TANK.}		250.00	-
			710.00	400.00
GRAND TOTAL			3,535.55	1,875.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CC4/FCI20012755/Uba3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBL 2101S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBL 2101S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

