



Co. Reg: 20135118W

Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883

• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date : 11/19/2020

TO: First Capital Insurance Limited  
36 Robinson Road #16-01  
City House  
Singapore 068877

Total Pages :

Our Customer : MUHAMMAD ALFI BIN SHAMSUDIN

Vehicle No : **FBL2101S**

Model : YAMAHA MTM 850A (XSR900)

Manufacture Year : 2016

Date of Accident : 11/14/2020

Total Estimate Repair Days : 7

Attn : Motor Claim Department

Email : [cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)

Re: Repair Estimate For Third Party Claim against : SHC7580K

| No.       | Item Descriptions                                       | Qty | Unit Price | Amount            | Remarks From Surveyor |
|-----------|---------------------------------------------------------|-----|------------|-------------------|-----------------------|
| <b>A.</b> | <b>Spare Parts</b>                                      |     |            |                   |                       |
| 1         | RH handle grip assembly                                 | 1   | \$32.00    | \$32.00           |                       |
| 2         | RH handle balancer                                      | 1   | \$18.50    | \$18.50           |                       |
| 3         | RH brake handle                                         | 1   | \$45.80    | \$45.80           |                       |
| 4         | Brake wireharness                                       | 1   | \$35.50    | \$35.50           |                       |
| 5         | RH side mirror                                          | 1   | \$135.00   | \$135.00          |                       |
| 6         | RH outer absorber fork                                  | 1   | \$280.00   | \$280.00          |                       |
| 7         | RH front fender bracket                                 | 1   | \$205.00   | \$205.00          |                       |
| 8         | Radiator side guide                                     | 1   | \$135.00   | \$135.00          |                       |
| 9         | RH radiator bottom hose                                 | 1   | \$16.50    | \$16.50           |                       |
| 10        | RH side guide assembly (engine)                         | 1   | \$98.00    | \$98.00           |                       |
| 11        | RH side guide - block slider assembly                   | 1   | \$165.00   | \$165.00          |                       |
| 12        | Front exhaust heat shield                               | 1   | \$120.00   | \$120.00          |                       |
| 13        | Rear exhaust heat shield                                | 1   | \$110.00   | \$110.00          |                       |
| 14        | Front brake padle                                       | 1   | \$220.00   | \$220.00          |                       |
| 15        | RH passenger foot rest bracket                          | 1   | \$19.50    | \$19.50           |                       |
| 16        | Guide - Stand arm bush assembly                         | 1   | \$58.00    | \$58.00           |                       |
| 17        | Brake padle guide                                       | 1   | \$210.00   | \$210.00          |                       |
| 18        | Petrol tank                                             | 1   | \$367.70   | \$367.70          |                       |
| 19        | Handle bar                                              | 1   | \$185.50   | \$185.50          |                       |
|           | <b>Sub Total</b>                                        |     |            | <b>\$2,457.00</b> |                       |
|           | Cost Plus 15%                                           |     |            | \$368.55          |                       |
|           | <b>Sub Total 1</b>                                      |     |            | <b>\$2,825.55</b> |                       |
|           |                                                         |     |            |                   |                       |
|           | <b>Total Spare Parts</b>                                |     |            | <b>\$2,825.55</b> |                       |
| <b>B.</b> | <b>Labour</b>                                           |     |            |                   |                       |
| 1         | Labour to replace handle bar and RH outer absorber fork |     |            | \$300.00          |                       |
| 2         | Top up coolant & do pressure test                       |     |            | \$80.00           |                       |
| 3         | To replace petrol tank                                  |     |            | \$80.00           |                       |
| 4         | To spray paint petrol tank                              |     |            | \$250.00          |                       |
|           | <b>Total Labour</b>                                     |     |            | <b>\$710.00</b>   |                       |
|           | <b>Total Repair Cost</b>                                |     |            | <b>\$3,535.55</b> |                       |
|           | <b>* The above quoted are exclusive of GST.</b>         |     |            |                   |                       |

Yours faithfully,

| Surveyor's Details |  |
|--------------------|--|
| Name               |  |
| Contact            |  |
| Survey Date        |  |



**Co. Reg: 20135118W**  
Auto Bay @ Kaki Bukit Blk 1 Area “A” Kaki Bukit Ave 6 #01-04 (S) 417883  
• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: [www.autoncars.com.sg](http://www.autoncars.com.sg)

\_\_\_\_\_  
*Venessa*  
*f Auto N Cars Services (Commercial) Pte Ltd*

|              |                           |
|--------------|---------------------------|
| Recommend    | Authorize / Not Authorize |
| Before Paint | Yes / No                  |
| Signature    |                           |