

CVE Aug 2025

ASSIGNMENT

CC4/III 2001 2759/Dba³

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SJY 45411 Yr Regn: Sept 2010

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Volkswagen Jetta c.c. 1390

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 340283 T/Radio: Insured / Std / NI / NA

Eng/No: CA X 531413

C/No: NVW Z 221KZA M 137808

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/55 R16

R: 11

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / M/C / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook

Front R/Bal. S mm L/Bal. S mm

Rear R/Bal. S mm L/Bal. S mm

D.O.A. 17/11/2020 D.O.I. 23/11/2020

Survey held at JWG AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>III GBH 149P</u>
	<u>MV 34K</u>
	<u>LIA 14.8K</u>
	<u>HL 19.2K</u>
<u>18/01/2021</u>	<u>from 2/5 9800/- site 7 days of repair</u>

Date/Time, File Pass to? : Preli. Report

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Date/Time, File Return to? _____

Report Format: _____

Lump Sum / L.B.F. (\$) _____

Add Fee: Site Insp (\$) _____

Interview (\$) _____

Tech. Invs (\$) _____

Weekend (\$) _____

Survey Fee:

Transportation: _____

S+RS SI _____

Photos _____

Others _____

TOTAL _____

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: NTUC INCOME INSURANCE CO-OP LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING XB9298D [YOUR INSURED] & SJY4541D [OUR CLIENT]
ON 27/10/2020.

ESTIMATED REPAIR COSTS FOR SJY4541D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BONNET <i>st / Dent</i>	839.60	\$ 1,472.35 ✓
1PC	BONNET LOCK <i>HH</i>		\$ 214.50 ✗
1PC	BONNET STRIKER LOCK <i>HH</i>		\$ 85.00 ✗
1PC	BONNET INSULATOR <i>HH</i>		\$ 273.00 ✗
2PCS	BONNET HINGE LH / RH @ \$68.25 EACH <i>o/s st w/s HH</i>		\$ 136.50 ✓
1PC	BONNET LOCK CABLE <i>HH</i>		\$ 285.70 ✗
1PC	FRONT WINDSCREEN <i>HH</i>		\$ 1,728.40 ✗
1PC	FRONT WINDSCREEN MOULDING <i>HH</i>		\$ 741.00 ✗
1PC	FRONT WINDSCREEN LOWER GARNISH <i>HH</i>		\$ 295.00 ✗
1PC	FRONT GRILLE <i>chrome Svc</i>		\$ 490.00 ✗
1PC	FRONT GRILLE BASE <i>crack / broken</i>	439.12	\$ 633.75 ✓
1PC	FRONT GRILLE LOGO <i>Svc</i>		\$ 130.65 ✗
1PC	HEAD LAMP RH <i>broken</i>	681.25	\$ 987.50 ✓
1PC	HEAD LAMP LOWER BRACKET RH <i>broken</i>		\$ 123.40 ✓
1PC	HEAD LAMP ECU RH <i>HH</i>		\$ 825.30 ✗
1PC	FRONT BUMPER <i>Dent</i>	846.15	\$ 981.50 ✓
1PC	FRONT BUMPER GRILLE <i>HH</i>		\$ 314.50 ✗
1PC	FRONT BUMPER FOG LAMP RH <i>HH</i>		\$ 189.15 ✗
1PC	FRONT BUMPER FOG LAMP GARNISH RH <i>HH</i>		\$ 97.50 ✗
1PC	FRONT BUMPER FOG LAMP HOLDER RH <i>HH</i>		\$ 89.50 ✗
1PC	FRONT BUMPER FOG LAMP WIREHARNES <i>HH</i>		\$ 1,184.20 ✗
1PC	FRONT BUMPER FOG LAMP TOP GARNISH RH <i>cut</i>		\$ 68.25 ✓
1PC	FRONT BUMPER LOWER LID <i>HH</i>		\$ 463.25 ✗
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$63.15 EACH <i>w/s HH</i>		\$ 126.30 ✓
1PC	FRONT BUMPER SPONGE <i>HH</i>		\$ 152.65 ✗
1PC	WIPER WASHER TANK <i>crack / broken</i>		\$ 458.00 ✓
1PC	WIPER WASHER MOTOR <i>HH</i>		\$ 170.00 ✗
1PC	WIPER WASHER HOSE <i>HH</i>		\$ 32.50 ✗
1PC	FRONT SUPPORT PANEL <i>broken / Dent</i>	879.15	\$ 1,782.90 ✓
1PC	RADIATOR RESERVE TANK <i>crack</i>	321.80	\$ 892.50 ✓

IPC	FUEL CANISTER <i>manly broken</i>		\$ 892.50	✓
IPC	A/C CONDENSOR <i>HH</i>		\$ 1,873.40	X
IPC	A/C CONDENSOR HIGH PRESSURE PIPE <i>HH</i>		\$ 572.50	X
IPC	A/C CONDENSOR LOW PRESSURE PIPE <i>HH</i>		\$ 562.40	X
IPC	A/C CONDENSOR DISCHARGE PIPE <i>HH</i>		\$ 772.30	X
IPC	RADIATOR ASSY <i>HH</i>		\$ 1,931.90	X
IPC	RADIATOR FAN MOTOR <i>HH</i>		\$ 396.20	X
IPC	RADIATOR FAN BLADE <i>HH</i>		\$ 339.50	X
IPC	RADIATOR FAN COWLING <i>HH</i>		\$ 485.20	X
IPC	FRONT FENDER RH <i>Buc</i>		\$ 792.40	✓
IPC	FRONT FENDER INNER SHIELD RH <i>detune / turn</i>		\$ 117.00	✓
IPC	FRONT FENDER BRACKET RH <i>1st</i>		\$ 287.50	✓
IPC	FRONT WHEEL HOUSING RH <i>Buc</i>	1139.20	\$ 1,849.29	✓
IPC	FRONT RIM RH <i>cut</i>	SN 450.00	\$ 1,072.50	✓
IPC	FRONT RIM HUB COVER RH <i>HH</i>		\$ 83.40	X
IPC	FRONT WHEEL BEARING & HUB RH <i>Dam</i>	345.00	\$ 690.00	✓
IPC	FRONT ABSORBER RH <i>distans</i>	489.73	\$ 559.35	✓
IPC	FRONT ABSORBER MOUNTING RH <i>HH</i>		\$ 97.50	X
IPC	FRONT ABSORBER LINK RH <i>HH</i>		\$ 78.00	X
IPC	FRONT ABSORBER STOPPER RH <i>HH</i>		\$ 35.10	X
IPC	FRONT ABSORBER DUST COVER RH <i>HH</i>		\$ 39.00	X
IPC	FRONT LOWER ARM RH <i>distans</i>	382.50	\$ 570.50	✓
IPC	FRONT KNUCKLE ARM RH <i>distans</i>	655.00	\$ 968.00	✓
IPC	FRONT STABILIZER LINK RH <i>HH</i>		\$ 70.20	X
IPC	FRONT STABILIZER BAR <i>HH</i>		\$ 448.50	X
IPC	FRONT TIE ROD RH <i>HH</i>		\$ 478.00	X
IPC	FRONT TIE ROD END RH <i>HH</i>		\$ 507.25	X
IPC	STEERING RACK & PINION ASSY <i>HH</i>		\$ 3,120.00	X
IPC	DRIVE SHAFT <i>HH</i>		\$ 2,340.00	X
IPC	FRONT CROSSMEMBER <i>HH</i>		\$ 1,825.00	X
IPC	GEAR BOX ASSY <i>HH</i>		\$ 17,940.00	X
IPC	GEAR BOX MOUNTING <i>HH</i>		\$ 228.15	X
IPC	FRONT ABS SENSOR RH <i>HH Dam / 1st</i>	383.65	\$ 980.20	✓
IPC	A PILLAR RH <i>HH</i>		\$ 1,035.82	X
IPC	A PILLAR CHROME MOULDING RH <i>HH</i>		\$ 195.20	X
IPC	FRONT DOOR RH <i>rep</i>		\$ 1,092.00	X
IPC	FRONT DOOR WINDOW MOULDING RH <i>HH</i>		\$ 195.00	X
IPC	FRONT DOOR CHROME MOULDING RH <i>HH</i>		\$ 205.00	X
IPC	ENGINE MOUNTING <i>HH</i>		\$ 497.80	X

PARTS SUM: \$ 61,648.31
 PARTS LESS 10%: \$ 6,164.83
 PARTS TOTAL: \$ 55,483.48

10272.60



9245.34

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY BONNET INNER TRIM CLIPS	2H	\$	50.00	X
*	TO SUPPLY HEAD LAMP CLIPS	4H	\$	50.00	X
*	TO SUPPLY FRONT GRILLE CLIPS	4EC	\$	50.00	20/-
*	TO SUPPLY FRONT BUMPER CLIPS	4EC	\$	50.00	30/-
*	TO SUPPLY FRONT BUMPER GRILLE CLIPS	4H	\$	50.00	X
*	TO SUPPLY FRONT BUMPER UNDER COVER CLIPS	4EC 2H	\$	50.00	X
*	TO SUPPLY FRONT FENDER INNER SHIELD CLIPS	4EC	\$	50.00	20/-
*	TO SUPPLY A PILLAR SEALANT	4H	\$	80.00	X
*	TO SUPPLY FRONT DOOR INNER TRIM CLIPS	4H	\$	50.00	X
*	TO SUPPLY COOLANT	4H	\$	150.00	X
				520.00	
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS		\$	500.00	80/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS		\$	2,000.00	1200/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS		\$	2,000.00	1800/-
*	TO TUFF COAT DAMAGED AREAS		\$	300.00	40/-
*	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS		\$	600.00	150/-
*	TO RNR GEARBOX TO FACILITATE REPAIRS		\$	1,500.00	44
				2540.00	
*	TO CONDUCT COMPUTERIZED 4 WHEEL ALIGNMENT		\$	120.00	60/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS		\$	200.00	30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS		\$	1,200.00	180/-

LABOUR & S/N TOTAL: \$ 9,050.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 64,533.48

23/11/2020 @ 1800hrs
 Not Antu
 4/5 same 7 days.

 J. Man
 LKK Antu


12305.34
 1/5 9800/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Check part prices.