

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 7242Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	TO REPAIR SEE LABOUR	2,052.42	-
1	BOOTLID REAR LOGO	NECESSARY	60.00	60.00
1	BOOTLID "7 G-TRONIC" EMBLEM	NECESSARY	75.00	75.00
1	BOOTLID "E 200" EMBLEM	NECESSARY	70.98	70.98
1	BOOTLID C&C LOGO	NECESSARY	48.00	48.00
1	BOOTLID WEATHERSTRIP	TORN	233.65	233.65
1	BOOTLID INNER LOCK	SERVICEABLE	295.00	-
1	REAR BUMPER	DENTED / DEFORMED	1,485.32	1,485.32
1	REAR BUMPER LOWER	DEFORMED	480.00	480.00
1	SET REAR BUMPER CLIPS	NECESSARY	60.00	60.00
4	REAR BUMPER PDC SENSORS @\$245.00	SHORTED (2 PCS ONLY)	980.00	490.00
2	REAR BUMPER EXHAUST CHROMES @\$205.00	SERVICEABLE	410.00	-
1	REAR END PANEL	BADLY DENTED	988.20	988.20
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	315.00	-
2	TAILLAMPS @\$598.30	O/S CRACKED	1,196.60	598.30
	LESS 10% DISCOUNT		-	-458.94
			8,750.17	4,130.51
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REPLACED PDC SENSOR.		100.00	50.00
	TO TRANSFER BOOTLID MECHANISM.	NOT NECESSARY	120.00	_
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		150.00	80.00
	TO SPRAY RUST PROOFING.		80.00	30.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID.		1,000.00	700.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	800.00
			3,030.00	1,680.00
	GRAND TOTAL		11,780.17	5,810.51

Report Ref No. CS/AGI20012763/Uqf3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,600.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/AGI20012763/Uqf3q2

CHUA KANG SENG
Licensed Appraiser