

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 56587**  
Date Estimated : **17/11/2020**  
Prepared By : **Brandon Chan Eng Meng**

**- ESTIMATE REPAIR FOR -**  
**Soh Ching Yau**  
**40 Pavilion View**

**- ACCOUNT - 158**  
**Lonpac Insurance Bhd**  
**300 Beach Road**  
**#17-04/07 The Concourse**  
**Singapore 199555**

**Singapore 658454**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SMU8634D</b>	<b>WBA5F32080FJ71687</b>	<b>31/08/2020</b>	<b>320i</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To make good rear bumper, rear left fender including knock out dented area, realign affected area and remove attachments to facilitate repair caused by the accident.	1,700.00		1,700.00
To respray rear bumper and rear left fender.	1,730.00		1,730.00
To check electrical wiring system and lighting at the rear section for proper function.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

### # SUPPLEMENTARY ITEMS

Total Labour :	3,660.00
Total Parts :	0.00
Total Labour & Parts :	3,660.00
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,660.00
GST @7%:	256.20
Grand Total :	3,916.20