



Bik 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklmotorsport.com.sg Website: www.hklmotorsport.com.sg

FBA8012J

Passer
Hp 90010068
6 days
4/5
20/11/2020
@ 1200
Rear after
repair

1	FRONT FORK ASSY LH/RH ?	\$2,400	3250
2	FRONT FORK UNDER BRACKET ?	\$680	
3	STEERING CONE BEARING ?	\$150	
4	FRONT FENDER X	\$250	
5	FRONT WHEEL RIM repair	\$750	
6	FRONT BRAKE DISC LH/RH RH-?/LH-X	\$800	
7	HANDLE BAR RH ?	\$220	
8	HANDLE BAR BALANCER sca	\$120	
9	BRAKE PUMP FREMBO sca	\$750	
10	TAIL BOARD CENTER cm	\$280	
11	TAIL BOARD LH cm	\$190	
12	TAIL BOARD RH cm	\$190	
13	RIDER SEAT X	\$220	
14	PILLIAN SEAT Tool	\$230	
15	PILLIAN SEAT LOCK cm	\$120	
16	PILLIAN SEAT LOCK CABLE X	\$55	
17	PILLIAN SEAT LOCK (KEY) X	\$95	
18	REAR FENDER ?	\$120	
19	REAR NO PLATE LIGHT X	\$95	
20	TAIL SHALF FRAME LH/RH cm	\$900	
21	TAIL SHALF FRAME BRACKET 2PCS cm	\$110	
22	REAR FOOT REST/BRACKET RH sca	\$195	
23	TAIL SHALF FRAME CENTER repair	\$450	
24	BRAKE PEADL sca	\$120	
25	FRONT FOOT REST RH sca	\$95	
26	FRONT FOOT REST BRACKET RH X	\$120	
27	FUEL TANK X	\$1,800	
28	EXHAUST INSPECTION rec - receipt	\$80	
29	EXHAUST MUFFLER cm	\$1,200	
30	REAR SIGNAL LH/RH sca	\$240	
31	TAIL LIGHT ho	\$220	
32	SIDE FAIRING RH INNER cm 4. cm	\$750	
33	SIDE FAIRING LH/RH OUTER cm	\$420	
34	FRAME SLIDER sca	\$150	
35	SPRAY PAINTING	\$1,200	400 600
36	LABOUR	\$950	400
37	TOWING	\$50	

Tool panel - \$95 ✓ CAA
Tool panel - \$95 ✓ CAA
TOTAL AMOUNT: \$16,765
Gao Qianp
CKK 04/11/2021
Fuel tank panel LH 1RH - \$240 - cm
Rear fender long panel - 220 ✓ CAA