

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 169876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg

Our Ref : LLH/rl/1328/1120/19AW

Your Ref : SJE 8298 K

10 9 NOV 2020

Brightstar Car Rental Pte. Ltd.
87 Defu Lane 10
#03-13
Singapore 539219

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING SKS 1919 M AND SJE 8298 K ON 24 JUNE 2020 ALONG PUNGGOL ROAD

We are instructed **Koh Saw Tin**, to claim damages against you or your insured, the driver of motor vehicle no. SJE 8298 K, in connection with a road traffic accident on 24th day of June, 2020, at about 18:40 hours along Punggol Road, involving our client's motor vehicle no. SKS 1919 M and motor vehicle no. SJE 8298 K driven by your insured at the material time.

We are instructed that the accident was caused by your insured's negligence and/or management of his motor vehicle. As a result of the accident, our client's motor vehicle was damaged and our client had been put to loss and expenses, particulars of which are as follows:

1	Costs of Repair	\$ 53,500.00
2	Loss of Use (\$250 x 58 days)	\$ 14,500.00
3	Towing fee	\$ 300.00
4	LTA/GIA	\$ 36.45
5	Survey fees	\$ 2,198.00
6	Disbursement (at this stage)	\$ 100.00
7	Legal Cost (at this stage)	\$ 1,200.00
		<u>\$ 71,834.45</u>



3019972276 --

By Certificate of Posting
(For your attention; without enclosures)

60196659

BY PDX NO. 8176



010809023057
FROM TOMMY CHOO, MARK GO LL
PDX Box No. 8141

100 VLN A

100 VLN A

TOMMY CHOO MARK GO LLC

Page No. 2

A copy each of the following supporting documents is enclosed:

1. Copy of accident report, traffic police report and LTA search;
2. Copy of accident report of SJE 8298 K;
3. Copy of traffic police letter dated 27th July 2020;
4. Copy of repair bill and towing receipt;
5. Copy of survey report and invoice; and
6. Colour photographs pertaining to our client's motor vehicle for your perusal;

Kindly note that if you are insured and you wish to claim from your insurance policy, you should immediately pass this letter to your insurer.

Please note that you should send us an acknowledgment of receipt of this letter within fourteen (14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send us a letter giving full particulars of the counterclaim together with the relevant documents within 8 weeks of your receipt of this letter.

Yours faithfully,



LING LEONG HUI (MR)

enc.

cc. clients

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/06/2020 07:57
Date Of Accident	24/06/2020 18:40
Exact Location Of Accident	TPE (SLE) EXIT SENGKANG EAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS1919M
Insured/Policyholder	
Name Of Registered Owner	KOH SAW TIN
NRIC No	SXXXX315H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90185314
Alternative Phone No	OTHERS-90185314
Vehicle Particulars	
Manufacturer	AUDI
Model	S3 SEDAN 2.0 TFSI QU (HID)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA525100/1
Cover Note Number	
Driver	
Name of Driver	TAN CHANG HUI JEREMY
NRIC No	SXXXX599B
Date Of Birth	08/08/1994
Occupation	INDOOR
Date Of Driving Pass	09/07/2013
Driving Experience	6 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92705882
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 19 TU FU AVENUE APORE 787226
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : FOO SHZE QIEN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN/POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJE8298K
 Vehicle Make/Model/Colour MITSUBISHI / COLTPLUSSPRT
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN CHANG HUI JEREMY

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKS1919M

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 2

Name FOO SHZE QIEN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKS1919M

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

Completed by the Policyholder and/or the Authorized Representative

¹ See, e.g., *California v. Shivers*, 1997 WL 10000 (9th Cir. 1997).

Sketch Plan #2

10-11-2016

TPE (SKE)
Exit Gangkang
Exit Road



A → Section 14

B → SITE EXITS

10-11-2016 CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

The following information was obtained from the police report:

On 10-11-2016, at approximately 10:00 AM, a vehicle labeled 'A' was traveling southbound on the main road. At the same time, a vehicle labeled 'B' was traveling northbound on the same road. The vehicles collided at the intersection of the main road and the exit road. The collision resulted in the vehicle labeled 'A' being damaged and the vehicle labeled 'B' being damaged. The driver of vehicle 'A' was not injured, but the driver of vehicle 'B' was injured. The driver of vehicle 'B' was transported to the hospital by ambulance. The accident was investigated by the police, and a police report was filed. The police report states that the driver of vehicle 'A' was at fault for the accident. The driver of vehicle 'A' was cited for failing to yield to the vehicle labeled 'B'.

10-11-2016

Signature of the driver of vehicle 'A'

Signature of the driver of vehicle 'B'

Signature of the police officer



**SINGAPORE
POLICE FORCE**



T/20200625/7001

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20200625/7001

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/06/2020 01:15		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TAN CHANG HUI JEREMY			Address: 19 TU FU AVENUE SINGAPORE 787226		
ID Type / ID No.: NRIC NO / S9428599B			Contact No.: Home/Office: Mobile: 92705882		
Nationality: SINGAPORE CITIZEN			Email: j-eremy@hotmail.sg		
Sex: Male	Age: 25	Date of Birth: 08/08/1994	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Self employed			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 24/06/2020 18:40	Type of Location: Straight Road
Location: PUNGGOL ROAD				
Weather: Raining		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJE8298K	Car					0
SKS1919M	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20200625/7001

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20200625/7001

CONTINUATION OF REPORT

Passenger				
Name	FOO SHZE QIEN		ID No.	S9643234H
Related Vehicle	SKS1919M (Car)		Contact No.	96741991
Hospital/Clinic	MOUNT ELIZABETH NOVENA HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	24/06/2020	Date Discharge	25/06/2020	
No. of Days granted Medical Leave	03	Degree of Injury	Serious	
Driver				
Name	TAN CHANG HUI JEREMY		ID No.	S9428599B
Related Vehicle	SKS1919M (Car)		Contact No.	92705882
Hospital/Clinic	MOUNT ELIZABETH NOVENA HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	24/06/2020	Date Discharge	25/06/2020	
No. of Days granted Medical Leave	03	Degree of Injury	Serious	

Brief Details.

On stated date and time, I was travelling straight in my vehicle bearing (SKS 1919 M). Suddenly a vehicle bearing (SJE 8298 K) cut right out from his lane into my lane, i horn and brake but couldnt stop in time. He collided onto the front left portion of my vehicle, pushing my vehicle onto the right side of the kerb and bushes. I then move over to my backseat to open the door as both my front doors were stuck. We exchange particulars and decided to proceed with insurance claims. I then went to mount elizabeth hospital as I felt pain in my back and head.



**SINGAPORE
POLICE FORCE**



T/20200625/7001

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20200625/7001

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
YEO GEAK ENG CECILIA
Contact No.: 65476404

Authentication Stamp

NP168

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:
25/06/2020 01:15

Classification Of Case:

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 24 Jun 2020 / 21:12:29

Receipt Date/Time : 24 Jun 2020 / 21:12:28

Tax Invoice/Receipt

Receipt No. : ITNET-00000-200624-003657

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SJE8298K As at 24 Jun 2020/18:40:00 Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SJE8298K Enquiry Fee 20200624211054053880	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	554827XXXXX9194	eNETS Credit Card		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

TAX INVOICE

Our Ref No: GR-20-075408
Date of Request: 26/06/2020

Your Ref No: PURCHASE BY EMAIL

NINETEEN AUTOWERKS PTE LTD
BLK 13 KAKI BUKIT ROAD 4 #01-05 BARTLEY BIZ CENTRE
SINGAPORE 417807

Dear Sir/Madam,

Date of Accident: 24/06/2020
Vehicle No: SKS1919M
Place of Accident: TPE (SLE) EXIT SENGKANG EAST ROAD
Involving Vehicle No: SJE8298K

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SJE8298K	TPE (SLE) EXIT SENGKANG EAST ROAD	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:
Date:
☐ GIRO ☒ Cash ☐ Cheque

TAX INVOICE

Our Ref No: GR-20-075407

Date of Request: 26/06/2020

Your Ref No: PURCHASE BY EMAIL

NINETEEN AUTOWERKS PTE LTD
BLK 13 KAKI BUKIT ROAD 4 #01-05 BARTLEY BIZ CENTRE
SINGAPORE 417807

Dear Sir/Madam,

Your Vehicle No: SKS1919M

Date of Accident: 24/06/2020

Place of Accident: TPE

Involving Vehicle No: SJE8298K

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/06/2020 20:35
Date Of Accident	24/06/2020 18:30
Exact Location Of Accident	TPE (SLE)TWDS SENGKANG EAST RD & PUNGGOL WAY EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJE8298K
Insured/Policyholder	
Name Of Registered Owner	BRIGHTSTAR CAR RENTAL PTE LTD
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	COLT-1.5 (A)
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	VFX/P2381791
Cover Note Number	
Driver	
Name of Driver	MOHAMAD HERMANTINO BIN DIFARI
IRIC No	SXXXX672C
Address	BLK 107 YISHUN RING ROAD #07-223
General Information of the Accident	
Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Other Information	
Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	5
Circumstances of Accident	
Report please refer to police report	
Attachment(s)	
Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO
DETAILS OF OTHER VEHICLE PROPERTY 1	
Vehicle Registration Number	SKS1919M

Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name

DETAILS OF INJURED PERSON 1

Name MOHAMAD HERMANTINO BIN DIFARI
Injured person in which vehicle? SJE8298K

DETAILS OF INJURED PERSON 2

Name TATIA
Injured person in which vehicle? SJE8298K

DETAILS OF INJURED PERSON 3

Name SAFURA
Injured person in which vehicle? SJE8298K

DETAILS OF INJURED PERSON 4

Name FAZLINA
Injured person in which vehicle? SJE8298K

DETAILS OF INJURED PERSON 5

Name ZAFIR
Injured person in which vehicle? SJE8298K

5. 中国进出口贸易总额: 4000 亿美元

[illegible]

1. $\frac{1}{2} \cdot \frac{1}{2} = \frac{1}{4}$ (probability of getting two heads)
 2. $\frac{1}{2} \cdot \frac{1}{2} = \frac{1}{4}$ (probability of getting two tails)
 3. $\frac{1}{2} \cdot \frac{1}{2} = \frac{1}{4}$ (probability of getting one head and one tail)
 4. $\frac{1}{2} \cdot \frac{1}{2} = \frac{1}{4}$ (probability of getting one tail and one head)

¹ *Consent under the Personal Data Protection Act (PDPA)

[illegible]

10) ~~restoring the accident victim's rights~~

[illegible]

47. All instruments which have not yet been revised or replaced in the schedule and the relevant category/ies above, shall be replaced on receipt. Use of clause 46/47 requires the Principal Institution to make a note of the above provision. A-1

14) My Personal Information will also be collected and used by credible claims history for the purpose of fraud detection, investigation and management in present and all future claims.

¹² In all matters and/or any other Third Parties that assist in publishing, investigating, conducting or managing fraud, regulators, the Enforcement and Investigation agencies are reasonably required for the purposes stated, or

Driver's Signature _____

Reporting Center Personnel's Signature _____

NAME: _____
 PERIOD: _____

Page 3 of 14

Sketch Plan #2

LETTERMAN

Vehicle A: SJL 829BK
Vehicle B: SKS 1919M



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time I, vehicle A was travelling straight on the stated road. Suddenly I felt a huge impact from the rear portion of my vehicle, my vehicle then lost control and spin causing my vehicle front portion hit onto the curb on my right. I my believe that is vehicle B that collided onto my vehicle.

DECLARATION

I/We only use the following particulars in this statement



Police Officer's Signature
Name & Title

Driver's Signature
(If driver is not the police officer)
Date & Time

Accident Scene Personnel's Signature
Name
Address

5713/3096



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408563
Tel +65 6547 0600
Fax +65 6547 4883
www.police.gov.sg

Our Ref : TP/IP/27413/2020
Date : 27 July 2020

**TAN CHANG HUI JEREMY
19 TU FU AVENUE
SINGAPORE 787226**

Dear Sir/Madam

ROAD TRAFFIC ACCIDENT INVOLVING SJE 8298 K AND SKS 1919 M ALONG PUNGGOL ROAD ON 24.06.2020 AT ABOUT 8.40PM

I refer to the above accident.

2. Please be informed that we have completed our investigations which revealed that the driver/rider of SJE 8298 K had committed an offence of **Careless Driving Causing Hurt** under **Section 65(1)(b) of the Road Traffic Act Chapter 276 p/u Section 65(4)(a) of the same Act**. Action has been initiated against the driver/rider for the said offence.
3. If you have any clarification, you may contact the Investigation Officer, Sergeant Sharifah Nor Farizan at office number: 65476172.
4. Thank you.

Yours faithfully

**HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.



Scanned with CamScanner
A FORCE FOR THE NATION

Nineteen Autowerks Pte Ltd

Blk 13 Kaki Bukit Road 4 #01-05

Bartley Biz Centre, Singapore 417807

Tel: (65) 9270 5882

Email: Nineteenautowerks@gmail.com



NINETEEN
AUTOWERKS

INVOICE NO. 19AW/TCMG/07/20

DETAILS

Koh Saw Tin
19 Tu Fu Avenue
Singapore 787226

Date: 19th October 2020

COST OF REPAIRS FOR VEHICLE NO. SKS 1919 M

Lump Sum Cost of Repairs: S\$53,500.00

Singapore Dollars: Fifty Three Thousand Five Hundred Only.

M/S NINETEEN AUTOWERKS PTE LTD

高 GAO

Express Towing Services

You Call, We Tow - Fast . Secured . Reliable



Blk 27 Marine Crescent Ville #10-01 Singapore 440027 Co. Reg. No. 53152603L H2: 500 900 92 Email: jim.koh@hotmail.com Website: <http://www.gaoexpresstowing.sg>

CASH SALE/WORK ORDER

寶號

Messrs: CASH

車號

Vehicle No: SKS199M

車型

Model No: ACD 32

時間(日/夜)

Time (day/night):

Contact No: _____

Location: TPE EXIT FUNG GOSLWAR

到

To: BARU 312

Cash \$: 300

其他

Others: _____

經手人

Authorised By: Jim

Tow Truck

Driver Name: Sever/9900

No. 181485

Date: 21/06/20

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☒ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

注意本公司對所拖之車輛,在進行中如有任何損失或破壞,一概由車主自行負責。
Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.



PRO-OPTION SERVICES

Mailing address: 81k 189B Rivervale Drive, #04-1004, Singapore 542189

Mobile: 9061 0543, Email: mirage1195@gmail.com

Koh Saw Tin
19 Tu Fu Avenue
Singapore 787226

Invoice no:	POS0177/20
Date:	19 October 2020
Report no:	177M0620.NA
Vehicle :	SKS1919M

INVOICE

No	Item Description	Qty	Unit Price	Total Amount(\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			2,198.00
SGD(\$): Two Thousand One Hundred and Ninty-eight only			Payable Amount:	2,198.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES

Authorised Signature



PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Mobile: 9061 0543, Email: mirage1195@gmail.com

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 177M0620.NA

Vehicle no : SKS1919M

1 REFERENCE

Date of inspection : 26 June 2020

Requested by : Koh Saw Tin
19 Tu Fu Avenue
Singapore 787226

Type of survey : Independent

Repairer : Nineteen Autowerks Pte Ltd
Blk 13 Kaki Bukit Road 4, #01-05, Bartley Biz Centre Singapore 417808

Date of accident : 24 June 2020

2 VEHICLE DATA

Make/model : **AUDI S3 SEDAN 2.0 TFSI QU (HID)**

Chassis no : WAUZZZ8V4F1089573

Engine no : CJX045329

Date of registration : 30 March 2015 COE Expiry Date: 29 March 2025

Engine capacity : 1984 cc

Odometer reading : 78172 km

Colour : Yellow

3 STATIC CONDITION CHECK

Steering : Affected
Foot brakes : Serviceable
Hand brakes : Serviceable
Paintwork : Good
General Condition : Fair

4 TIRE CONDITION CHECK

	<u>RH/MAKE</u>	<u>LH/MAKE</u>	<u>SIZE</u>
Front tread	6 mm/Michelin	6 mm/Michelin	225/40R18
Rear tread	6 mm/Michelin	6 mm/Michelin	225/40R18

5 BRIEF DESCRIPTION OF DAMAGE

Front bumper broken, LH headlamp broken, RH headlamp leg broken, LH front fender crushed, RH front fender buckled/distorted, carbon fibre front bonnet dented/cracked, front suspension & undercarriage parts damaged, rear bumper grazed/tab broken, RH rear fender dented/bent/distorted, RH rear door dented/bent, RH front door grazed, wing mirror grazed, RH rear suspension & undercarriage parts damaged, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : **\$53,500.00** (lump sum)

Estimated no of days : **Fifty-eight (58)**

8 ASSESSMENT OF DAMAGE AND COSTSReport no: 177M0620.NAVehicle no: SKS1919M**A SPARE PARTS**

<u>Description</u>	<u>Qty</u>	<u>Assessed Condition</u>	<u>Repairer's Amount</u>	<u>Revised Amount</u>
Front bumper	1	broken	1,652.00	1,652.00
Front bumper reinforcement	1	dented/bent	613.00	613.00
Front bumper side retainer	2	necessary	70.00	70.00
Front bumper clip	10	necessary	50.00	50.00
LH HID Xenon headlamp assy	1	broken	1,210.00	1,210.00
LH headlamp spray jet	1	broken	270.00	270.00
LH Hid headlamp spray jet cover	1	dislodged/missing	70.00	70.00
RH HID Xenon headlamp assy	1	legs broken	1,210.00	1,210.00
Front grille c/ logo set	1	broken	900.00	900.00
Front grille clip set	8	necessary	40.00	40.00
Front number plate holder	1	tab broken	86.00	86.00
LH front fender	1	crushed	710.00	710.00
LH front fender splash shield	1	torn	250.00	250.00
LH front fender splash shield clip	8	necessary	40.00	40.00
LH/RH front shock absorber	2	bent	2,876.00	2,876.00
LH/RH front suspension lower arm	2	bent	478.00	478.00
LH/RH front driver shaft	2	bent/wobbled/scraped	3,700.00	3,700.00
LH/RH front steering knuckle	2	bent/distorted	2,042.00	2,042.00
LH/RH front wheel bearing c/w hub assy	2	rattled/noisy	1,252.00	1,252.00
LH/RH stabiliser bar link	2	bent/twisted	302.00	302.00
LH steering tie rod	1	bent	135.00	135.00
LH steering tie rod end	1	bent	112.00	112.00
LH/RH suspension ball joint	2	bent	210.00	210.00
Front stabilizer bar	1	bent	385.00	385.00
Steering rack & pinion assy	1	rack bent/joint	4,520.00	4,520.00
Front suspension cross member	1	bent/distorted/scraped	1,505.00	1,505.00
Engine front splash cover	1	cracked	128.00	128.00
Engine side splash cover LH	1	cracked	95.00	95.00
Horn set	1	dented/shorted	155.00	155.00
RH front fender	1	buckled/distorted	710.00	710.00
RH front fender splash shield	1	torn	250.00	250.00
RH front fender splash shield clip	8	necessary	40.00	40.00
RH front door	1	to repair/repaint	2,610.00	0.00
RH front door outer handle	1	grazed	135.00	135.00
Rear wheel bearing c/w hub assy	1	rattled/noisy	626.00	626.00
Rear shock absorber RH	1	bent	680.00	680.00
Rear trailing arm RH	1	bent	550.00	550.00
Rear wheel carrier RH	1	bent/distorted	1,020.00	1,020.00
Rear door RH	1	dented/bent	2,520.00	2,520.00
Rear RH door outer handle	1	grazed	128.00	128.00
Rear bumper	1	grazed/tab broken	1,250.00	1,250.00
Rear bumper side bracket RH	1	broken	96.00	96.00
Rear bumper clip	10	necessary	50.00	50.00
Taillamp assy RH	1	lens grazed/bracket bent	580.00	580.00
Rear fender RH	1	dented/bent/distorted	2,100.00	2,100.00
Rear RH fender splash shield	1	bent/deformed	155.00	155.00
Rear RH fender splash shield clip	10	necessary	50.00	50.00
Rear windscreen c/w moulding set	1	necessary	3,254.00	3,254.00
Front sport rim LH	1	abraded	1,630.00	1,630.00

Report no: 177M0620.NA
Vehicle no: SKS1919M

Front sport rim RH	1	broken	1,630.00	1,630.00
Rear sport rim RH	1	abraded	1,630.00	1,630.00
		Subtotal of the above	46,760.00	44,150.00
		Discount	10% / 10%	4,676.00
		Subtotal 1:	42,084.00	39,735.00
(Special nett)				
Carbon fribre front bonnet	1	bent/cracked	2,888.00	2,888.00
Carbon fibre front bumper lip	1	broken	1,180.00	1,180.00
Ccarbon fibre front bumper diffuser	1	broken	1,350.00	1,350.00
Carbon fibre side skirt	1	broken/scraped	1,750.00	1,750.00
Carbon fibre air filter housing cover	1	dented/cracked	980.00	980.00
LH fog lamp assy	1	dislodged/missing	250.00	250.00
LH fog lamp garnish	1	abraded	125.00	125.00
RH fog lamp assy	1	to reuse	250.00	250.00
RH fog lamp garnish	1	to reuse	125.00	0.00
Fog lamp bulb socket	2	broken	70.00	70.00
Turbo intercooler	1	dented/twisted/distorted	1,300.00	1,300.00
Turbo ineercooler grille	1	broken	95.00	95.00
Turbo intercooler bracket	1	bent/distorted	155.00	155.00
Turbon intercooler triple hose connector	1	broken	85.00	85.00
Rear tyre RH	1	Side wall cut	650.00	650.00
		Subtotal 2:	11,253.00	11,128.00

Total cost of parts:	53,337.00	50,863.00
----------------------	-----------	-----------

B LABOUR

To check wiring.	120.00	60.00
To apply anti-rust undercoat.	250.00	150.00
To align headlamps and focus headlamp beams to LTA specifications.	200.00	120.00
To remove , renew and install steering rack & pinion assy and to align steering geometry and centralise steering wheel. To hook up ECU to diagnoptic scanner, programme and set steering angle position.	800.00	600.00
To remove and replace front LH/RH suspension parts, suspension cross member, etc.	1,500.00	1,000.00
To conduct computerised 4-wheel alignment to reset wheel alignment.	120.00	90.00
To remove and refit rear passenger, rear fender inner trim cover anf fittings, affected upholstery and carpet, etc to facilitate the necessary repairs.	600.00	450.00
To remove and install rear windscreen glass to facilitate the necessary repairs.	200.00	150.00
Labour charges to remove and replace, to cut and weld, to panel beating affected and damaged parts.	3,600.00	3,000.00
Spray painting charges to paint the rear bumper, rear RH fender, rear RH door, front RH door, RH wing mirror, RH front fender, front bumper, LH front fender, LH windscreen pillar and necessary areas.	3,000.00	2,700.00
Towing and recover services (king dolly).	200.00	200.00

Total cost of labour:	10,590.00	8,520.00
-----------------------	-----------	----------

Total cost of repair:	63,927.00	59,383.00
-----------------------	-----------	-----------

Report no: 177M0620.NA
Vehicle no: SKS1919M

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is \$59,383.00

(a) The recommended cost of repair based on lump sum repairs would be **\$53,500.00**

(b) Number of days taken by the repairs would be **Fifty-eight (58)**
(1st Reinspection conducted on 29 June 2020)
(Post Repair Inspection conducted on 22 August 2020)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Prepared by:

.....
Liaw Leong San
Licensed Automotive Appraiser

Dated: 19 October 2020

Report no: 177M0620.NA

Vehicle no: SKS1919M



Report no: 177M0620.NA

Vehicle no: SKS1919M



Report no: 177M0620.NA

Vehicle no: SKS1919M



Report no: 177M0620.NA

Vehicle no: SKS1919M

