



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Unit: Jaslin

Car Number: SKC1637K

Model: Hyundai Elantra

Damaged Area: (Rear Left Side Portion)

Repairer Estimation Cost of Repair:

Supplementary may be included during the cost of repair:

Not Authorized
Make

20/11/20

d/s 2500

4 days

Take photo After rep-

Parts / Material:

1	Bootlid panel	11	\$ 1,128.00	X
2	Bootlid inner trim garnish	11	\$ 356.00	X
3	Bootlid hinge @ SGD 78.00	11	\$ 156.00	X
4	Bootlid centre garnish	11	\$ 175.00	X
5	Bootlid logo	11	\$ 98.00	X
6	Bootlid Emblem (Hyundai)	11	\$ 78.60	X
7	Bootlid Emblem (Elantra)	11	\$ 78.40	X
8	Bootlid Emblem (GLS)	11	\$ 68.40	X
9	Bootlid inner lock	11	\$ 195.00	X
10	Bootlid lock sensor	11	\$ 186.00	X
11	Bootlid lamp LH	11	\$ 586.00	X
12	Bootlid weather strip	11	\$ 245.00	X
13	Taillamp LH	11	\$ 786.00	X
14	Taillamp panel LH	11	\$ 197.00	X
15	Rear bumper	11	\$ 967.00	X
16	Rear bumper side retainer @ SGD 68.00	11	\$ 136.00	X
17	Rear bumper bracket @ SGD 78.00	11	\$ 156.00	X
18	Rear bumper reflector @ 164.00	11	\$ 328.00	X
19	Rear bumper reinforcement	11	\$ 370.00	X
20	Rear bumper plastic lower bracket	11	\$ 228.00	X
21	Rear bumper top bracket @ 130.00	11	\$ 260.00	X
22	Rear bumper lower garnish	11	\$ 280.00	X
23	Rear bumper keyless sensor	11	\$ 258.00	X
24	Rear bumper clips (Set)	11	\$ 60.00	X
25	Rear fender LH	11	\$ 1,418.00	X
26	Rear fender lower extension LH	11	\$ 486.00	X
27	Rear fender inner shield	11	\$ 198.00	X
28	Rear fender inner shield clips (Set)	11	\$ 60.00	X
29	Rear fender inner trim garnish	11	\$ 386.00	X
30	Rear fender inner trim garnish clips (Set)	11	\$ 60.00	X
31	Rear spare tyre top garnish	11	\$ 245.00	X
32	Rear spare tyre panel	11	\$ 894.00	X
33	Rear spare tyre top side panel @ SGD 270.00	11	\$ 540.00	X
34	Rear end panel	11	\$ 580.00	X
35	Rear end panel top garnish	11	\$ 145.00	X

Parts: \$12,388.40

Less Parts 20%: \$ 2,477.68

Total Parts: \$ 9,910.72

P-1911-80
20%
1529.44

Special Net Items :

Sundries	1 1	\$ 50.00	X
Bootlid sealant	1 1	\$ 60.00	X
Windscreen glass inner seal	1 1	\$ 190.00	X
Windscreen glass sealant	1 1	\$ 80.00	X
Rear parking sensor	1 1	\$ 280.00	X
Rear number plate w/garnish	1 1	\$ 60.00	X
Rear end panel sealant	1 1	\$ 60.00	50
Rear spare tyre panel insulator (accessories)	1 1	\$ 450.00	X
Total S/N Parts :		\$ 1,230.00	

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$ 1,200.00	800
To Putty, Spray Paint on Affected Accident Areas	\$ 1,200.00	600
To Check & Re-Connect all electrical wiring	\$ 50.00	20
To Remove & Install Rear Bootlid Trim, Garnish	1 1 \$ 200.00	X
To Remove & Install Rear Bootlid Interior Components	1 1 \$ 200.00	60
To Remove & Install Rear Windscreen Glass	1 1 \$ 200.00	X
To Remove & Install, Align Reverse Sensor	\$ 120.00	50
To Conduct Water Leakage Test	1 1 \$ 150.00	X
To Rust Proof Affected Areas	\$ 150.00	30
Total Labour :		\$ 3,470.00

TOTAL PARTS :	\$ 9,910.72
TOTAL SPECIAL NET ITEM :	\$ 1,230.00
TOTAL LABOUR :	\$ 3,470.00
TOTAL REPAIR COST :	\$ 14,610.72

DATE OF SURVEY / INSPECTED:
 RECOMMENDED PART BY PART / LUMP SUM :
 RECOMMENDED NUMBER OF DAYS :
 SURVEY BY / SURVEYOR FIRM :
 RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
 FINALISED AMOUNT :

7-1529.44
 S/N- 50.00
 2-1580.00
 3139.44
 206
 2571.53

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: