



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI20012784/Kqf3e2	
			Date: 29/01/2021	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 6389Y	Veh. Inspected	SMD 4512M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D20004739MFSH	Excess (\$)	0.00	
Assign From	VICSANGHILAN	Assign Date	20/11/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	ZVW305123307	Colour	METALLIC PEARL WHITE	
Odometer	319503 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	GREMAX	9 mm	
L/H Front Tyre	185/65 R15	GREMAX	9 mm	
R/H Rear Tyre	185/65 R15	DUNLOP	3 mm	
L/H Rear Tyre	185/65 R15	DUNLOP	3 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/11/2020	Inspection Date	23/11/2020	
Survey held at	BLK 7 #01-92 SIN MING IND EST SEC C			
Repairer	V8 MOTOR WERKZ PTE LTD			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	