

V8 MOTOR WERKZ PRIVATE LIMITED

7 #01-92 SIN MING INDUSTRIAL ESTATE SINGAPORE 575642
TEL NO : 91442977
EMAIL : V8MOTORWERKZ@GMAIL.COM
ROC NO. : 201622378N

NOT AUTHORIZED
11 Sep @ 1200h
Mummy After Rain
3 days

DATE : 23/11/2020
MAKE / MODEL : TOYOTA PRIUS 1.5 HYBRID
VEHICLE PLATE NUM : SMD4512M

ESTIMATE:

No.	Description	QTY	Amount
1	REAR END PANEL LOCK STRIKER	Det 1	\$85.70 ✓
2	REAR END PANEL	n 1	\$696.30 X
3	REAR BUMPER	Bu 1	\$531.10 ✓
4	REAR BUMPER SIDE RETAINER	Dis 1	\$100.40 ✓
5	REAR END PANEL WEAHTERSHIP	Pl 1	\$372.30 X
6	REVERSE SENSOR	shc 1	\$200.00 ✓
7	FOR REPLACE REVERSE SENSOR 259	1	\$60.00 501
8	LABOUR CHARGE FOR DISMANTLE AND REPLACEMENT OF ACCIDENT PARTS. TO HEAT/WELD CUT-OFF TAILLAMP PANEL, INCLUDING KNOCKING, REPAIRING, STRAIGHTEN, RESHAPE AND ADJUST OF THE SAME	1	\$600.00 400(
9	TO PUTTY AND SPRAY PAINT INNER / OUTER ON REAR END PANEL , REAR BUMPER	1	\$400.00 ✓
0	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	1 n	\$120.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: