



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Honda Noah SMV155S Hybrid

No	Qty	Parts Description	Estimated Parts Price
1	1	Bumper assy / def	\$ 1,500.00 1,025
2	1	Bumper right bracket X SVC	\$ 105.00x
3	1	Bumper retractor / BR	\$ 105.00 ✓
5	1	RR taillamp X SVC	\$ 850.00x
6	1	Taillamp lower bracket X SVC	\$ 97.50x
7	1	Fender X R	\$ 682.30x
8	1	Wheel cowling X SVC	\$ 285.00x
		Parts sub-total	\$ 3,624.80

1,130
-25%
847.5



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Honda Noah SMV155S Hybrid

No	Qty	Parts Description	Estimated Parts Price
		<u>Special Nett Items</u>	
1	10	Bumper clips <i>/Nec</i>	\$ 50.00 <i>30</i>
2	6	Fender inner cowling clips <i>X Svc</i>	\$ 40.00 <i>X</i>
3	1	Quarter glass sealant <i>X Svc</i>	\$ 60.00 <i>X</i>
5	1	Rim <i>X R</i>	\$ 850.00 <i>X</i>
		Special Nett Items	<u>\$ 1,000.00</u> <i>30</i>
		Total parts	\$ 4,624.80



Xin Yun Auto Private Limited
 幸运汽车服务有限公司
 Tel: 6634 0858 Email: xinyunauto1@gmail.com
 Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Honda Noah SMV155S Hybrid

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,000.00 <i>300</i>
2	To putty and spray painting front portion, front bumper, side fender, door touch up, side mirror, bonnet side touch up	\$ 1,200.00 <i>600</i>
3	To check wiring and focus taillamp.	\$ 60.00 <i>X</i>
4	To apply anti rust proofing to front affected area.	\$ 120.00 <i>40</i>
5	To remove and check undercarriage parts, axel need to check, as the alignment result shows the wrong reading	\$ 180.00 <i>X</i>
6	To balance wheel.	\$ 60.00 <i>X</i>
7	To conduct wheel alignment.	\$ 100.00 <i>X</i>
9	To remove and install rear bumper sensor.	\$ 80.00 <i>X</i>

Repair day - 2 days

Total labour : \$ 2,800.00 *940*

*L/S
After paint photo*

Total parts : 4,624.80
Total labour : 2,800.00
Total repair cost : 7,424.80

*Sun Pin (LKK)
05/01/2020*

*L/S
\$ 1,450
2 day*

*847.5
30
940

1,817.5
- 20%

1,454*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: