

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Nadaraja, Deeban

Date: 24 Nov 2020

## **Preliminary Advice**

Vehicle No	: GBD4419E	Accident Date	: 30/10/2020
Make	: TOYOTA HIACE	Policy No.	: 1900232580
Assignment Date	: 20/11/2020	Excess	: S\$800.00
Date of Inspection	: 20/11/2020	Est. Duration of Repair	: 14
Inspection At	: TEAM AUTOPRO PTE LTD (SIN MING) (HQ) 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY SINGAPORE 575722		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	45,717.58
Revised Amount	:S\$	9,080.33
Check Items (Estimated)	:S\$	27,632.60
Total	:S\$	36,712.93

Lump Sum Repair	:S\$	
-----------------	------	--

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	39,000.00
COE / PARF Rebate	:S\$	13,921.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,079.00

## **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :