



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:

19/11/2020

Vehicle:

GBJ2976U

Make / Model:

KIA K2500

Chassis No:

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	TAILGATE / DD	1	\$ 1,798.00	\$ 1,798.00
2	TAILGATE SAFETY LOCK X Svc	2	\$ 214.00	\$ 428.00
3	TAILGATE LOWER END PANEL X Svc	1	\$ 812.00	\$ 812.00
4	TAILGATE HINGES X Svc	3	\$ 65.00	\$ 195.00
5	TAILGATE KIA MOTOR STICKER / NEC	1	\$ 240.70	\$ 240.70
6	TAILAMP BRACKET / BT	2	\$ 296.00	\$ 582.00
7	TAILAMP / CRA	2	\$ 412.00	\$ 824.00
8	REAR CROSSMEMBER X Svc	1	\$ 1,125.00	\$ 1,125.00
9	REAR EXHAUST PIPE X Svc	1	\$ 712.00	\$ 712.00
10	REAR SPARE TYRE BRACKET X Svc	1	\$ 312.00	\$ 312.00
11	REAR NUMBER PLATE LAMP / CRU	1	\$ 124.00	\$ 124.00
12	REVERSE BUZZER / shut	1	\$ 159.00	\$ 159.00
			10%	\$ 7,311.70
			Less 20%	\$ 1,462.34
			Total	\$ 5,849.36
S/Nett items:				
1	REAR NUMBER PLATE / CRU	1	\$ 50.00	\$ 50.00
2	REVERSE SENSOR WITH HOLDER / shut	1	\$ 300.00	\$ 300.00
3	TAILGATE ALUMINIUM PLATE X Svc	1	\$ 800.00	\$ 800.00
4	REAR FLOOR PANEL ALUMINIUM PLATE / DD	1	\$ 1,200.00	\$ 1,200.00
5	TAILGATE STICKER 70KM / NEC	1	\$ 50.00	\$ 50.00
6	TAILGATE STICKER 13PAX / NEC	1	\$ 50.00	\$ 50.00
7	REAR LOWER SAFETY BAR / BT	1	\$ 1,500.00	\$ 1,500.00
8	REAR LOWER SAFETY BAR BRACKET X NN	2	\$ 200.00	\$ 400.00
				\$ 4,350.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00
3	REMOVE AND REFIX TAILGATE ALUMINIUM PLATE	1	\$ 300.00	\$ 300.00
4	REMOVE AND REFIX TAILGATE MECHANISM	1	\$ 150.00	\$ 150.00
5	TO WELD SAFETY BAR	1	\$ 200.00	\$ 200.00
6	TO RESPRAY UNDERCOATING	1	\$ 100.00	\$ 100.00
7	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00
8	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,600.00	\$ 1,600.00
9	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,600.00	\$ 1,600.00
				\$ 4,300.00

Repair dys - 5 dys

L/S

Repair after paint photo

Sm Pin (L/L)

20/11/2020

Parts Replacement Amount

\$ 10,199.36

5,609.23

- 20%

4,487.38

L/S

\$ 4,500

5 dys

Total Amount for Labour	\$ 4,300.00
Total Amount	\$ 14,499.36

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: