

ealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

20 NOV 2020

E S T I M A T E

Estimate No. : b1 56622
Date Estimated : 20/11/2020
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lee Kok Yong, Allan
134 Bedok Reservoir Road
#05-1225

Singapore 470134

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMV7676J	WBA5F32080FJ64240	20/10/2020	320i	0

DESCRIPTION**VALUE**

To replace rear bumper and attachments.

850 ~~1,275.00~~

To painting rear bumper.

934 1,038.00

To check electrical wiring sys tem and lighting at the rear s
ection for proper function.150 ~~171.00~~To remove old PDC assembly, re place damaged parts and re conn
ect to new bumper including re connet to new bumper and condu
ct check for proper function.150 ~~171.00~~

Sundries

? 80.00

Total Labour 1: 2,747.00

DESCRIPTION**QTY****PRIC****VALUE**TAILPIPE TRIM CHROME D=90MM *scr -*

1

124.00

124.00

REAR BUMPER CARRIER ?

1

479.65

479.65

ADAPTER ?

1

48.40

48.40

REAR BUMPER LH SIDE GUIDE ?

1

58.25

58.25

REAR BUMPER LH TRIM PANEL REAR TOP ?

1

95.35

95.35

REAR BUMPER LH BOTTOM TRIM PANEL (L ?

1

96.00

96.00

REAR BUMPER PANEL PRIMED (BASIS PDC *de*

1

1,274.95

1,274.95

Total Parts : 2,176.60

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 56622
Date Estimated : 20/11/2020
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMV7676J	WBA5F32080FJ64240	20/10/2020	320i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 01/12/2020 @ 1045 Excess S\$ _____

Surveyor's Name PABUL Sign _____

Surveyor's Tel 900 10068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days



Labour 1	:	2,747.00
Parts	:	2,176.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	344.65
Grand Total	:	5,268.25