

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

20 NOV 2020

ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 56622
Date Estimated : 20/11/2020
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Lee Kok Yong, Allan
134 Bedok Reservoir Road
#05-1225

Singapore 470134

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMV7676J	WBA5F32080FJ64240	20/10/2020	320i	0

DESCRIPTION

To replace rear bumper and attachments.

To painting rear bumper.

To check electrical wiring system and lighting at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including reconnect to new bumper and conduct check for proper function.

Sundries

VALUE

850 1,275.00

934 1,038.00

150 177.00

150 177.00

? 80.00

Total Labour 1: 2,747.00

DESCRIPTION	QTY	PRIC	VALUE
TAILPIPE TRIM CHROME D=90MM <i>see XSC</i>	1	124.00	124.00
REAR BUMPER CARRIER <i>?bt</i>	1	479.65	479.65
ADAPTER <i>?ca</i>	1	48.40	48.40
REAR BUMPER LH SIDE GUIDE <i>?XSC</i>	1	58.25	58.25
REAR BUMPER LH TRIM PANEL REAR TOP <i>?XSC</i>	1	95.35	95.35
REAR BUMPER LH BOTTOM TRIM PANEL (L <i>?XSC</i>	1	96.00	96.00
REAR BUMPER PANEL PRIMED (BASIS PDC <i>de</i>	1	1,274.95	1,274.95
Total Parts :			2,176.60

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 56622
Date Estimated : 20/11/2020
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

EN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
7676J	WBA5F32080FJ64240	20/10/2020	320i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / <u>3rd Party</u> / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time <u>01/12/2020 @ 1045</u>	Excess S\$ _____
Surveyor's Name <u>PABUL</u>	Sign _____
Surveyor's Tel <u>900 10068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>3 days</u>	

Labour 1	:	2,747.00
Parts	:	2,176.60