

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 01 Feb 2021

**Preliminary Advice**

Insured Vehicle No	: YQ383J		
TP Vehicle No	: SMJ2674K	Accident Date	: 18/11/2020
Make	: BMW X2	Assignment Date	: 20/11/2020
Date of Inspection	: 07/12/2020	Est. Duration of Repair	: 7
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,751.70
Revised Amount	:S\$	14,134.75
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,134.75
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :