


Section A - Accident Details

Registration Number	SHF176A
Case Reference Number	TAX/11/20/2032
Registration Date	26/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	YEOH LYE SAN(YANG LAISHAN)
Type of Accident	Rear To Head
Accident Date and Time	16/11/2020 1:45 PM
Accident Reported Date and Time	17/11/2020 11:59 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108805
Special Instruction to ARC, if any	REAR LEFT DAMAGE / TOWED \$40
Prepared Date and Time	17/11/2020 2:22 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,145.00	\$500.00
Total Spray Cost	\$2,196.00	\$600.00
Total Spare Part Cost	\$12,117.68	\$1,727.41
Total Other Cost	\$656.00	\$90.00
TOTAL COST	\$16,114.68	\$2,917.41 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	20/11/2020 4:05 PM	21/11/2020 8:44 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	P/P, Before paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION LH	\$845.00	\$300.00 ✓
TO REPAIR REAR END PANEL	\$300.00	\$200.00 ✓
Total Labour	\$1,145.00	\$500.00 154pp 500

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY LH RAIL ROOF SIDE	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00 ✓
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00 ✓
Total Spray Painting & Panel Beating	\$2,196.00	\$600.00 154pp 600

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$40.00
Total Other Costs	\$656.00	\$90.00 90

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	25.00	\$364.20	Replace	Replace ✓
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$332.70	0.00	\$0.00	Replace	Check X
		52462-47130	PAD, RR BUMPER, RH & LH, 3	1.00	\$11.00	25.00	\$8.25	Replace	Replace ✓
		52462-47030	PAD, RR BUMPER, RH & LH, 2	1.00	\$4.00	25.00	\$3.00	Replace	Replace ✓
		52462-47020	PAD, RR BUMPER, RH & LH, 1	1.00	\$4.00	25.00	\$3.00	Replace	Replace ✓
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$11.00	25.00	\$24.75	Replace	Replace ✓

CR4
SVC
NEC
NEC
NEC
NEC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 02/12/2020

User ID PohSuan

52575-47060	RETAINER, RR BUMPER, RH	1.00	\$132.60	25.00	\$99.45	Replace	Replace	✓	BR
52576-47060	RETAINER, RR BUMPER, LH	1.00	\$132.60	25.00	\$99.45	Replace	Replace	✓	BR
52591-47080	SEAL, RR BUMPER, RH	0.00	\$118.30	0.00	\$0.00	Replace	Not Given	X	SVC
52592-47080	SEAL, RR BUMPER, LH	0.00	\$118.30	0.00	\$0.00	Replace	Check	X	SVC
52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace	✓	Nec
52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$374.50	25.00	\$280.88	Replace	Replace	✓	CRU
52169-47070	COVER, GUARD RR BUMPER LOWER	0.00	\$22.00	0.00	\$0.00	Replace	Not Given	X	SVC
81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$39.00	0.00	\$0.00	Replace	Not Given	X	SVC
81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	0.00	\$39.00	0.00	\$0.00	Replace	Check	X	SVC
58398-47050	COVER, REAR FLOOR UNDER, RH	0.00	\$175.10	0.00	\$0.00	Replace	Not Given	X	SVC
58399-47030	COVER, REAR FLOOR UNDER, LH	0.00	\$241.90	0.00	\$0.00	Replace	Check	X	SVC
66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$229.90	0.00	\$0.00	Replace	Check	X	SVC
81561-47471	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$339.60	0.00	\$0.00	Replace	Check	X	SVC
81498-47040	COVER, REAR COMBINATION LAMP, LH	0.00	\$69.90	0.00	\$0.00	Replace	Check	X	SVC
81456-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$261.00	0.00	\$0.00	Replace	Check	X	SVC
81590-47070	LAMP ASSY, REAR, LH	0.00	\$293.60	0.00	\$0.00	Replace	Check	X	SVC
61018-47010	MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	0.00	\$288.50	0.00	\$0.00	Replace	Not Given	X	SVC
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓	Nec
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X	SVC
61602-47180	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$871.50	100.00	\$0.00	Replace	Repair	✓	R
65638-47060	LINER, REAR FENDER, LH	0.00	\$139.80	0.00	\$0.00	Replace	Check	X	SVC
62940-47010	DUCT ASSY, QUARTER VENT, RH & LH	0.00	\$67.00	0.00	\$0.00	Replace	Check	X	SVC
4261147450	WHEEL, DISC	0.00	\$1,879.40	0.00	\$0.00	Replace	Not Given	X	SVC
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SVC
58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$651.00	0.00	\$0.00	Replace	Check	X	SVC
58311-47130	SPARE TYRE PANEL, PAN, REAR FLOOR	0.00	\$583.40	0.00	\$0.00	Replace	Not Given	X	SVC
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	SVC
76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$913.60	100.00	\$0.00	Replace	Repair	✓	R
64790-47060-C0	TAILGATE TRIM, UPPER	0.00	\$52.10	0.00	\$0.00	Replace	Not Given	X	SVC
67937-47060-C0	TAILGATE TRIM, RH	0.00	\$95.60	0.00	\$0.00	Replace	Not Given	X	SVC
67938-47060-C0	TAILGATE TRIM, LH	0.00	\$95.60	0.00	\$0.00	Replace	Not Given	X	SVC
67751-47111-C0	TAILGATE TRIM, LOWER	0.00	\$225.20	0.00	\$0.00	Replace	Not Given	X	SVC
67750-47080-C0	TAILGATE BOARD ASSY	0.00	\$259.20	0.00	\$0.00	Replace	Not Given	X	SVC
76085-47916	SPOILER SUB-ASSY, REAR	0.00	\$1,575.40	0.00	\$0.00	Replace	Not Given	X	SVC
75441-47220	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$54.60	25.00	\$40.95	Replace	Replace	✓	Nec
75403-48010	EMBLEM SUB-ASSY REAR	1.00	\$47.90	25.00	\$35.93	Replace	Replace	✓	Nec
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓	Nec
	STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓	Nec
84840-47040	SWITCH ASSY, BACK DOOR OPENER	0.00	\$179.10	0.00	\$0.00	Replace	Not Given	X	SVC
TMKONG-TAILG	AUTO TAILGATE SYSTEM	0.00	\$2,520.00	0.00	\$0.00	Replace	Not Given	X	SVC
Total			\$14,372.14		\$1,143.01				

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 02/12/2020
User ID PohSuan

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-47030	REAR BUMPER REINFORCEMENT	1.00	\$332.70	25.00	\$249.53	Replace	Replace
		81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1.00	\$39.00	25.00	\$29.25	Replace	Replace
		81561-47471	LENS & BODY, REAR COMBINATION LAMP, LH	1.00	\$339.60	10.00	\$305.64	Replace	Replace
Total					711.30		584.42		

BT
SCR
SCR

1727.43 /
+ 500.00 /
+ 690.00 /

2917.43 /

P/P
\$2,917.43

3 days