

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

28-Nov-20

Our ref : OD/0128/20

To : Sompoo Insurance Singapore Pte Ltd

Attn : Motor claims Dept.

RE :Supplementary cost for vehicle no : SKP 8338J

1 pc	logo base <i>encl'd</i>	\$	50.00	✓
1 pc	frt bumper frame top <i>encl'd</i>		63.00	✓
1 pc	pressure sensor <i>encl'd</i>		128.00	✓
2 pcs	basic mounting <i>3pc</i>		176.00	✓
2 pcs	side stability		30.00	✓
2 pcs	frt bumper frame rh lh <i>encl'd</i>		88.00	✓
2 pcs	struct <i>But</i>		72.00	✓
1 pc	mounting console <i>Damaged</i>		138.00	✓
1 pc	centre engine dust cover <i>encl'd</i>		122.00	✓
1 pc	2nd radiator <i>But</i>		598.00	✓
2 pcs	radiator side bracekt rh lh <i>encl'd</i>		116.00	✓
1 pc	brace panel <i>But</i>		53.00	✓
1 pc	intercooler air duct lower <i>encl'd</i>		105.00	✓
2 pcs	under cover bracket <i>encl'd</i>		44.00	✓
2 pcs	frt bumper later support <i>encl'd</i>		30.00	✓
			1,813.00	
			Csot plus 10%	
			181.30	
			1,994.30	
			Plus 7% GST	
			139.60	
			2133.90	

SD : Two thousand one hundred thirty-three & cents ninety only.

30/11/20.
Resurveyed

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____
--

Supplementary: 1994.30

Total: 18004.50

(P/P)