

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20012812/QBA3Q2
Date: 27/06/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SJW1011Y	Insured Vehicle No :	SH7102B
Date of Loss:	13/11/2020	Nature of Claim:	TP
		Claim No:	MCT20110255

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW1011Y	Engine No:	PE20704858
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Chassis No:	JM6GJ1072G0222575
Reg. Date:	30/11/2015 (Man. Year: 2015)	Odometer:	60767 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55Z R17	Rear Tyre Size:	225/55Z R17
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	926.20	864.60	61.60	6.65
Miscellaneous Items	329.52	228.29	101.23	30.72
Labour	525.00	205.00	320.00	60.95
Paintwork Labour	601.99	601.99	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,382.71	1,899.88	482.83	20.26
Approved Total (Overridden) (S\$)		1,888.88		

(S\$)	2,382.71	1,888.88	493.83	20.73
+ GST 7.00/7.00% (S\$)	166.79	132.22	34.57	20.73
Nett Amount (S\$)	2,549.50	2,021.10	528.40	20.73
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		2,321.10		

INSPECTION

Date of Assignment:	20/11/2020	Present Location:	Hua Hong Pte Ltd (Sungei Kadut)
Date Inspected:	23/11/2020	Inspected At:	Hua Hong Pte Ltd (Sungei Kadut) 10 Kaki Bukit Avenue 4, #04-63 Premier @ Kaki Bukit Singapore 415874
Estimated Period of Repair:	3.0 days		

Adjuster: OI SUN PIN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jun 2021)
Parts:	143	MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW1011Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*L/FITTING COVER (WCP)	Missing	18.00 F	*18.00 F
2	1	NA	*L/OUT BUMPER BRACKET (WCP)	Necessary	25.00 F	*25.00 F
3	1	NA	*L/R BUMPER REFLECTOR (WCP)	Not Necessary	28.00 F	*- F
4	1	NA	*R/FITTING COVER (WCP)	Missing	18.00 F	*18.00 F
5	1	NA	*R/OUT BUMPER BRACKET (WCP)	Necessary	25.00 F	*25.00 F
6	1	NA	*R/R BUMPER REFLECTOR (WCP)	Not Necessary	28.00 F	*- F
7	1	NA	*REAR BUMPER (WCP)	Crumpled	450.00 F	*450.00 F
8	1	NA	*REAR BUMPER SUPPORT (WCP)	Bent	225.00 F	*225.00 F
9	1	NA	*SCREW M5X16 (WCP)	Necessary	25.00 F	*25.00 F
					Sub Total (S\$)	842.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	84.20
					Total Parts (S\$)	926.20
						786.00
						78.60
						864.60

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	REVERSE SENSOR X4 1 SET (SHORTED)	300.00	200.00
2	1	SUNDRY	18.52	17.29
3	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$)	329.52
				228.29

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	425.00	425.00
2	Total Paint Materials	New	176.99	176.99
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	525.00	205.00
			Gross Labour Cost (\$)	1,126.99
				806.99

Report was unsubmitted during this print-out.

< END OF ESTIMATES >