

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

TEL: 64616555

ATTN: Motor Claim Department

Your Ref No: SLA142B

Claim Type: Own Damage

Accident Date: 18/11/2020

Estimate No: MCS1900355

Date: 19 Nov 2020

Policy No: D20MTPV01009731

Veh Reg No: SLA142B

Make/Model: KIA FORTE K3



Not Notarized
Repair By paint

6 days

85523.50

Ex: TBA

Estimate Repair Cost to Vehicle No : SLA142B

Description	U/Price	Quantity	Cost	Amount
			SS	SS
SPARE PARTS				
1 FRONT BONNET		1 PC	340.00	✓
2 FRONT BONNET INSULATOR		1 PC	65.00	✓
3 FRONT BONNET INSULATOR CLIP		8 PC	8.00	✓
4 FRONT BONNET HINGE L/R		2 PC	30.00	✓
5 FRONT BONNET LOCK		1 PC	28.00	✓
6 FRONT FENDER L/R		2 PC	300.00	✓
7 FRONT FENDER COWLING CLIP		14 PC	14.00	✓
8 FRONT BUMPER		1 PC	220.00	✓
9 FRONT BUMPER SIDE RETAINER L/R		2 PC	10.00	✓
10 FRONT BUMPER CENTRE TOP BRACKET		1 PC	20.00	✓
11 FRONT BUMPER INNER SPONGE		1 PC	48.00	✓
12 FRONT BUMPER CLIP		20 PC	20.00	✓
13 HEADLAMP L/R		2 PC	1,480.00	✓
14 RADIATOR GRILLE		1 PC	85.00	✓
15 GRILLE BADGE		1 PC	20.00	✓
16 RADIATOR SUPPORT PANEL		1 PC	220.00	✓
17 RADIATOR AIR GUIDE L/R		2 PC	16.00	✓
18 AIR CON CONDENSER		1 PC	280.00	✓
19 RADIATOR FAN ASSY		1 PC	260.00	✓
20 WIPER WASHER TANK		1 PC	40.00	✓
21 AIR INTAKE DUCT		1 PC	8.00	✓
22 AIR INTAKE DUCT HOSE		1 PC	55.00	✓
23 NO PLATE GARNISH		1 PC	8.00	✓
			3,575.00	
			357.50	3,932.50
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
Acknowledged by Repairer			Add 10%	
Signature:				
Date:				
Special Nett				
24 NO PLATE		1 PC	30.00	✓
25 RADIATOR COOLANT		1 PC	35.00	✓
				65.00
LABOUR				
26 TO CHECK WIRING AND REFOCUS HEADLAMP		1 PC	30.00	200
27 TO DISMANTLE AND REFIT AIRCON CONDENSER AND REFILL WITH AIRCON GAS		1 PC	120.00	1000
28 TO REMOVE AND REFIT WIPER MOTOR, WIPER ARM BLADE		1 PC	50.00	✓



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department
Your Ref No: SLA142B
Claim Type: Own Damage
Accident Date: 18/11/2020

Estimate No: MCS1900355
Date: 19 Nov 2020
Policy No: D20MTPV01009731
Veh Reg No: SLA142B
Make/Model: KIA FORTE K3

Estimate Repair Cost to Vehicle No : SLA142B

Description	U/Price	Quantity	Cost	Amount
			SS	SS
29 TO DISMANTLE AND INSTALL DAMAGE PARTS, TO REMOVE, REFIT AND ALIGN FRONT SUPPORT PANEL. TO KNOCK AND REPAIR FRONT AFFECTED AREA AND TO REFIT LISTED PARTS BACK SAME.		1 PC	800.00	600
30 TO SPRAY BONNET, BONNET HINGE L/R, FRONT FENDER LH, FRONT FENDER RH, FRONT BUMPER AND TOUCH UP FRONT BOTH SIDE DOOR.		1 PC	1,000.00	800
				2,000.00

Lump Sum Repair SS 5,997.50

Add GST @ 7% 419.83

Total Amount payable SS 6,417.33

TOTAL: SINGAPORE DOLLAR SIX THOUSAND FOUR HUNDRED SEVENTEEN AND CENTS THIRTY THREE ONLY

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE