

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

| No : 199405410K Invoice Name & Address | Owner Name & Vehicle Info | | | |
|---|---------------------------|------------------------------------|--|--|
| | Cust No/Name | /Dinesh Subramaniam | | |
| AIG Asia Pacific Insurance Pte. | Reg No/Reg Date | SLP1881R / 05/06/201 | | |
| Ltd. MOTOR CLAIM DEPARTMENT | Date In/Mileage | | | |
| 78 SHENTON WAY #08-16 | Chassis No | KNAPH81BMH5349104 | | |
| AIG BUILDING | Engine No | D4HBHH319055 | | |
| SINGAPORE 079120 Contact No 64191000 | Make/Model | KIA/SORENTO2.2ASXSRGBV3 | | |
| Contact No 04131000 | Colour/Trim | 4SS SILKY SILVER / WK SATURN BLACK | | |

| Account No | Terms | Date/Time Printed | CSE | Operator | | WIP No | | ALCOHOLD THE |
|---|--|--|--|---|-----------|------------|-------|--|
| LAX00000 | Credit | 20/11/2020/ 17:2 | 100000000000000000000000000000000000000 | 282 / Kevin L | eong | 24490 | | |
| LAXUUUUU | Creare | Description of Go | 1 TO | | Qty | Unit Price | Disc% | Amount |
| PAINT WO E PNT88000 REMOVE & M SUNDRY TO TOP LE E PNT88000 TO REPLA M SUNDRY TO APPL M SUNDRY TO APPL M SUNDRY TO APPL M SUNDRY PERFORM E PNT88000 TO REMO A 54900099 CHECK W A 10028901 TO CARR USING H A 99000099 RENEW S A 99000099 RENEW S M SUNDRY | ORK ON FR INSTALL JP AIRCON ACE FRONT Y WINDSCR LY WINDSCR Y SEALANT RUST PRE VE & INST JIRING & () AT OUT DIA AT OUT DIA AT OUT DIA BY OU | ER, HOOD, FRT LH IT T BUMPER, HOOD, FI RADIATOR, CONDEN GAS WINDSCREEN GLASS EEEN SEALANT CREEN SOLAR FILM T ON AFFECTED ARE EVENTION TALL FRONT PARKING CHASSIS ELECTRICAL AGNOSTIC CHECK US: | FENDER, SUPPORT LH FENDER SER FOR FACIL ASSIST SYSTEM ING HI-SCAN P | RT & AFFECTED AF & FRT LH DOOR .ITATE REPAIR RO TEST | REA 4 000 | | | 12000.00 1400.00 1400.00 120.00 240.00 240.00 220.00 100.00 100.00 400.00 200.00 400.00 100.00 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | | | |
|---|---------------------------|------------------------------------|--|--|
| | Cust No/Name | /Dinesh Subramaniam | | |
| AIG Asia Pacific Insurance Pte. | Reg No/Reg Date | SLP1881R / 05/06/201 | | |
| Ltd. MOTOR CLAIM DEPARTMENT | Date In/Mileage | 20/11/2020/ 0 | | |
| 78 SHENTON WAY #08-16 | Chassis No | KNAPH81BMH5349104 | | |
| AIG BUILDING | Engine No | D4HBHH319055 | | |
| SINGAPORE 079120 Contact No 64191000 | Make/Model | KIA/SORENTO2.2ASXSRGBV3 | | |
| Contact No 01232000 | Colour/Trim | 4SS SILKY SILVER / WK SATURN BLACK | | |

| Account No | Terms | Date/Time Pr | rinted | CSE | Ope | erator | | WIP No | | |
|------------|------------|---------------|----------|------------|-------|---------------|------|------------|---------------------|--|
| LAX00000 | Credit | 20/11/2020/ | | QUK | 282 | / Kevin Leong | | 24490 | | |
| LAXOUUU | Oreare | Description | | s / Servic | es | | Qty | Unit Price | Disc% | Amount |
| M SUNDRY | | - СССИ, | | | 20/10 | agreement | | | | 320.00 |
| TO APPL' | ZERTONA | COATING ON A | AFFECTED | AREA | 710 | | 4 00 | 67.00 | 20 00 | NM × 53.60 |
| | | MP WASHER | | | | | 1.00 | | 20.00 | dis 170.40 |
| M TELESCO | PE UNTT A | SSY-HEAD LAM | Ρ, | | | | 1.00 | 213.00 | | de 14.40 |
| | ELESCOPE, | | | | | | 1.00 | | 20.00 | CM 1768.00 |
| | SY-HEAD,L | | | | | | 1.00 | 2210.00 | | CM 64.80 |
| | SY-HIGH P | | | | | | 1.00 | 81.00 | | £594.40 |
| M RADIATO | | | | | | | 1.00 | 743.00 | | × (3×627.20 |
| | ER ASSY-C | OOLER | | | | | 1.00 | 784.00 | Same Street and the | m 2 252.80 |
| | ASSY-OIL | | | | | | 1.00 | 316.00 | 20.00 | 7 232.00 |
| M BLOWER | | r | | | | | 1.00 | 1063.00 | | 23.20° |
| M DAM-AIR | | | | Q51 | | 300 | 1.00 | | 20.00 | ny X 34.40 |
| M AIR GUI | | | | 5 | 1111 | ma | 1.00 | | 20.00 | 100 |
| M AIR GUI | | | | | | ППСТ | 4.00 | 77.00 | 20.00 | 61.60 648.00 |
| M INTERCO | | | | | | | 1.00 | 810.00 | 20.00 | act 1179.20 |
| | ASSY-PAS | SENGER | | | | | 1.00 | 1474.00 | | , 11/3.20 |
| | | WHEEL AIR B | AG | | | | 1.00 | 1536.00 | | , 1220.00 |
| | SSY-STEER | | | | | | 1.00 | 1493.00 | | 1131.10 |
| | SSY-HOOD | | | | | | 1.00 | 1654.00 | | |
| | SSY-HOOD, | LH | | | | | 1.00 | | 20.00 | 2 |
| | SSY-HOOD, | | | | | | 1.00 | | 20.00 | |
| | ENDER RR | | | | | | 1.00 | | 20.00 | uy × 37.60 |
| | ENDER, LH | • | | | | | 1.00 | | 20.00 | by 401.60 |
| | OR-FENDER | R LH | | | | | 1.00 | | 20.00 | 1-67 05.20 |
| | MPLETE-F | | | | | | 1.00 | 551.00 | | |
| M CARRIER | ASSY-FRO | ONT END MODUL | E | | | | 1.00 | | 20.00 | , |
| | D INSULA | | | | | | 1.00 | | 20.00 | |
| | ASSY FR-HO | | | | | | 1.00 | | 20.00 | M - 21.60 |
| | ASSY-WIND | | | | | | 1.00 | 1326.00 | | Control of the contro |
| | NG-WINDSH | | | | | | 1.00 | | 20.00 | |
| | | GLASS SIDE, | RH | | | | 1.00 | | 20.00 | |
| M MOULDI | MG-M/SHLD | GLASS SIDE, | I.H | | | | 1.00 | | 20.00 | |
| | ASSY-COWL | | | | | | 1.00 | 182.00 | 20.00 | 145.60 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. Page 2 of 3



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

Authorized signatory and company stamp

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | | | | |
|---|---------------------------|------------------------------------|--|--|--|
| | Cust No/Name | /Dinesh Subramaniam | | | |
| AIG Asia Pacific Insurance Pte. | Reg No/Reg Date | SLP1881R / 05/06/201 | | | |
| Ltd. MOTOR CLAIM DEPARTMENT | Date In/Mileage | | | | |
| 78 SHENTON WAY #08-16 | Chassis No | KNAPH81BMH5349104 | | | |
| AIG BUILDING | Engine No | D4HBHH319055 | | | |
| SINGAPORE 079120 Contact No 64191000 | Make/Model | KIA/SORENTO2.2ASXSRGBV3 | | | |
| Contact No 04151000 | Colour/Trim | 4SS SILKY SILVER / WK SATURN BLACK | | | |

| Account No Terms | Date/Time Pr | rinted | CSE | Operator | | WIP No | | |
|--|--|--|--|--|--------------|--|--|---|
| LAX00000 Credit | | A SHARL SHOW A SHA | QUK | 282 / Kevin Leong | | 24490 | | |
| LINOUGO C. G. G. S. | Description | | s / Services | | Qty | Unit Price | | Amount |
| M COVER-FR BUMPER M MOUNTING ASSY-LI M COVER ASSY-RADIA M GRILLE ASSY-RADIA M GRILLE-FRONT BUM M COVER-FR BUMPER M SKID PLATE-FR BI M LIP-FRONT BUMPEI M ABSORBER-FRONT M GRILLE-FRONT BUM M STIFFENER ASSY- M BRACKET-FR BUMP M WIRING HARNESS- M ULTRASONIC SENS M ULTRASONIC SENS M GUARD ASSY-FRON M S/BELT ASSY-FR M SEAT BELT PRETE M BUCKLE ASSY-FR M BUCKLE ASSY-FR M S/BELT ASSY-FR M S/BELT ASSY-FR M S/BELT ASSY-FR M CRASH PAD ASSY- | UPR ICENCE PLATE ATOR GRILLE UP IATOR MPER JUMPER BUMPER ENERGY MPER FOG LAMP FR BUMPER LWR ER SIDE, LH FR BUMPER OR ASSY-BWS T WHEEL, LH RH NSIONER, RH S/BELT, RH S/BELT, LH LH MAIN SU DA | LINE LINE THE POST OF SIGNATURE ACTIONS ACTION | Repairer of the control of the contr | d terls ray phinting d part(s) during resurvey bject to confirmation is on a "Without Prejudice" basis tion(s) is allowed m(s) must be resurveyed and pproval from Insurance Company | 1.00 July | 186.00 738.00 178.00 645.00 220.00 65.00 134.00 117.00 296.00 187.00 187.00 471.00 276.00 97.00 | 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 | 516.00 29.60 29.60 29.60 29.60 29.60 29.60 29.60 20 142.40 20 20 20 20 20 20 20 20 20 20 20 20 20 |
| Confirm & accepted | i by | | | | 7% GST on | | ett .20 | 25,061.2 1754.2 |
| | | | | | _ | otal Paya | h1. | 26,815.4 |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.