



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101750

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 18/03/2021
Reference CC4/FCI20012838/Urs3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. JSL 3207
Insured Veh. SHC 8158R
Claim No. D20004753MFSH
Policy No. D-20094922MFSH
Accident Date 14/11/2020
Inspection Date 23/11/2020

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CC4/FCI20012838/Urs3q2 Date: 18/03/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8158R	Veh. Inspected	JSL 3207
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20004753MFSH	Excess (\$)	0.00
Assign From	RACHEL WU	Assign Date	23/11/2020
2. Vehicle Particulars & Condition			
Make & Model	KAWASAKI EX250 -L	c.c	249
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	PNKEX250LLMCA5873	Colour	GREEN / BLACK
Odometer	90816 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	110/70-17	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/60-17	PIRELLI	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/11/2020	Inspection Date	23/11/2020
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JSL 3207

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER	CRACKED	285.00	180.00
2	FORK TUBES ASSY	BENT	3,464.00	960.00
1	FORK UNDER BRACKET	TO REPAIR SEE LABOUR	985.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	75.00	-
1	FRONT BRAE DISC	SERVICEABLE	609.00	-
1	FRONT SPORT RIM	TO REPAIR SEE LABOUR	1,950.00	-
1	TOP COWLING	CRACKED	645.00	590.00
1	LAMP STAY	TO REPAIR SEE LABOUR	509.00	-
1	HEADLAMP	CRACKED	1,250.00	820.00
1	SIDE MIRROR -L/H	CUT	165.00	90.00
1	HANDLE -BAR	NOT NECESSARY	255.00	-
1	HANDLE -BAR END -L/H	SCRATCHED	60.00	35.00
1	SET HAND GRIP	NOT NECESSARY	50.00	-
1	CLUTCH LEVER	BENT	155.00	155.00
1	SET FRONT SIGNALS	CRACKED	90.00	90.00
1	FRON SIGNAL OUTER GARNISH	CRACKED	385.00	385.00
1	SIDE FAIRING -R/H	CRACKED	338.00	338.00
1	SIDE FAIRING INNER PANEL -R/H	NOT NECESSARY	135.00	-
1	RADIATOR	NOT NECESSARY	1,848.00	-
2	FRONT FOOTREST	N/S CUT	170.00	60.00
2	FRONT FOOTRESTS BRACKETS	NOT NECESSARY	270.00	-
1	GEAR PEDAL	TWISTED	185.00	115.00
1	REAR FOOTREST -L/H	SERVICEABLE	85.00	-
1	FUEL TANK	NOT NECESSARY	1,820.00	-
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	1,250.00	-
1	REAR SIGNAL -L/H	NOT NECESSARY	90.00	-
1	REAR FAIRING	CRACKED	515.00	515.00

Report Ref No. CC4/FCI20012838/Urs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,763.80	-433.30
			15,874.20	3,899.70
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	NECESSARY	28.00	10.00
2	FORK OILS (SN)	NECESSARY	40.00	40.00
2	FORK OIL SEALS (SN)	NECESSARY	76.00	76.00
1	SET STEERING CONE (SN)	NECESSARY	120.00	80.00
1	FRONT TYRE (SN)	NOT NECESSARY	200.00	-
			464.00	206.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE (LOD) .		60.00	60.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO RESPRAY PAINTING.	NOT NECESSARY	600.00	-
	TO PROVIDE LABOUR .INCLUSIVE OF THE REPAIR OF FORK UNDER BRACKET ,FRONT SPORT RIM ,LAMP STAY AND EXHAUST PIPE .		480.00	300.00
			1,220.00	360.00
	GRAND TOTAL		17,558.20	4,465.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00

Report Ref No. CC4/FCI20012838/Urs3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. JSL 3207

INSPECTION








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. JSL 3207

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

