

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

email: erofia@singnet.com.sg

First

Name : Delip Uthayakumar

not Alhail

Accident Date : 14-Nov-20

Vehicle No : JSL3207

2 days. d/s #3000/ limited Repair

Vehicle Model : Kawasaki EX250-L

Estimated Repair Costs *together with Alhail's*

Qty	Description List Items	Amount S(\$)
1	Front fender <i>180</i>	<i>cm</i> \$ 285.00 ✓
2	Fork tubes assy <i>480x2=960</i>	<i>bat</i> \$ 3,464.00 ✓
1	Fork under bracket	<i>n</i> \$ 985.00 X
1	Front rim shaft	<i>n1</i> \$ 75.00 X
1	Front brake disc	<i>su</i> \$ 609.00 X
1	Front sport rim	<i>R</i> \$ 1,950.00 X
1	Top cowling <i>590</i>	<i>cm</i> \$ 645.00 ✓
1	Lamp stay	<i>n</i> \$ 509.00 X
1	Headlamp <i>820</i>	<i>cm</i> \$ 1,250.00 ✓
1	Side mirror - L/H <i>90</i>	<i>cm</i> \$ 165.00 ✓
1	Handle-bar	<i>n1</i> \$ 255.00 X
1	Handle-bar end - L/H <i>35</i>	<i>scr</i> \$ 60.00 ✓
1	Hand grip (1 set)	<i>n1</i> \$ 50.00 X
1	Clutch lever	<i>bat</i> \$ 155.00 ✓
1	Front signals (1 set)	<i>cm</i> \$ 90.00 ✓
1	Front signal outer garnish	<i>cm</i> \$ 385.00 ✓
1	Side fairing - R/H	<i>cm</i> \$ 338.00 ✓
1	Side fairing inner panel - R/H	<i>n1</i> \$ 135.00 X
1	Radiator	<i>n1</i> \$ 1,848.00 X
2	Front footrests <i>60</i>	<i>n/s (n)</i> \$ 170.00 <i>ipc</i>
2	Front footrests brackets	<i>n1</i> \$ 270.00 X
1	Gear pedal <i>115</i>	<i>n1</i> \$ 185.00 ✓
1	Rear footrest - L/H	<i>su</i> \$ 85.00 X
1	Fuel tank	<i>n1</i> \$ 1,820.00 X
1	Exhaust pipe	<i>n</i> \$ 1,250.00 X
1	Rear signal - L/H	<i>n1</i> \$ 90.00 X
1	Rear fairing	<i>cm</i> \$ 515.00 ✓
		\$ 17,638.00
	Less 10%	\$ 1,763.80
		\$ 15,874.20

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

email: erofia@singnet.com.sg

Name : Delip Uthayakumar

Accident Date : 14-Nov-20

Vehicle No : JSL3207

Vehicle Model : Kawasaki
EX250-L

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	1 set	\$	28.00	10
2	Fork oils	1 set	\$	40.00	✓
2	Fork oil seals	1 set	\$	76.00	✓
1	Steering cone (1 set)	80	\$	120.00	✓
1	Front tyre	1 set	\$	200.00	X
			\$	464.00	

S/No. Labour

1	To provide towing service (LOD)		\$	60.00	✓	
2	To check wiring and reset headlamp focusing		1 set	\$	80.00	X
3	To respray painting		1 set	\$	600.00	X
4	To provide labour	300	\$	480.00		
			\$	1,220.00		

Grand Total \$ 17,558.20

Singapore Dollars: Seventeen Thousand Five Hundred and Fifty-Eight and Cents: Twenty only 4405.7

3524

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: