



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 30/10/2020

ESTIMATE

NO : QUOT202011-000058(00)

DATE : 19/11/2020

POLICY NO : 999995580

VEH REG NO : GBH5253M

MAKE/MODEL : MERCEDES VITO

CHASSIS NO : WDF44760323328432

ENGINE NO : 65195034177790

REG. DATE : 2017 29/6/2018

Not Authorised
May be T6015

Estimate Repair Cost to Vehicle No : GBH5253M

| Description | Quantity | Unit Price | Amount |
|--|----------|-----------------|--------------|
| | | S\$ | S\$ |
| PARTS | | | |
| 1 Front windscreen glass | 1 | 720.00 | CM 720.00 ✓ |
| 2 Roof top panel | 1 | 1,550.00 | R 1,550.00 ✓ |
| 3 Roof top lining | 1 | Return 920.00 | 920.00 ✓ |
| 4 Dashboard assy | 1 | CM 1,150.00 | 1,150.00 ✓ |
| 5 Steering air bag | 1 | Arm 2,450.00 | 2,450.00 ✓ |
| 6 Passenger air bag | 1 | " 2,450.00 | 2,450.00 ✓ |
| 7 Air bag control unit | 1 | na 980.00 | 980.00 ✓ |
| 8 Front safety belt - RH / LH | 2 | Tn 800.00 | 1,600.00 ✓ |
| 9 Front safety belt buckle - RH / LH | 2 | 220.00 | 440.00 ✓ |
| 10 Front safety belt adjuster - RH / LH | 2 | 125.00 | 250.00 ✓ |
| 11 Front safety belt - centre | 1 | 800.00 | 800.00 ✓ |
| 12 Front safety belt buckle - centre | 1 | 120.00 | 120.00 ✓ |
| 13 Battery cut off switch | 1 | 350.00 | 350.00 ✓ |
| 14 Bonnet | 1 | Bz 850.00 | 850.00 ✓ |
| 15 Bonnet hinge - RH / LH | 2 | Dis 68.00 | 136.00 ✓ |
| 16 Bonnet cable | 1 | Tn 55.00 | 55.00 ✓ |
| 17 Support panel | 1 | CM 280.00 | 280.00 ✓ |
| 18 Support panel top garnish | 1 | CM 95.00 | 95.00 ✓ |
| 19 Support panel bracket - LH | 1 | mis 24.00 | 24.00 ✓ |
| 20 Brace panel | 1 | R 78.00 | 78.00 X |
| 21 Front wheel house panel -- LH | 1 | Bz 680.00 | 680.00 ✓ |
| 22 Front chassis frame -- LH | 1 | R 2,500.00 | 2,500.00 X |
| 23 Front longitudinal member - LH | 1 | 955.00 | 955.00 ✓ |
| 24 Front fender - RH / LH | 2 | Dis/Bz 550.00 | 1,100.00 ✓ |
| 25 Front fender inner shield - RH / LH | 2 | CRN/mis 125.00 | 250.00 ✓ |
| 26 Front fender inner shield flap - LH | 1 | 30.00 | mis 30.00 ✓ |
| 27 Front fender inner shield clips - RH / LH | 40 | 5.50 | na 220.00 ✓ |
| 28 Front fender signal lamp - LH | 1 | 38.00 | mis 38.00 ✓ |
| 29 Headlamp assy - RH | 1 | MSUM 850.00 | 850.00 ✓ |
| 30 Headlamp assy - LH | 1 | mis/Bz 1,800.00 | 1,800.00 ✓ |
| 31 Headlamp control unit - LH | 1 | mis 655.00 | 655.00 ✓ |
| 32 Headlamp control module - LH | 1 | mis 950.00 | 950.00 ✓ |
| 33 Front bumper | 1 | 750.00 | mis 750.00 ✓ |
| 34 Front bumper reinforcement | 1 | 420.00 | Bz 420.00 ✓ |



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000 FAX : 6415 3723
YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 30/10/2020

ESTIMATE

NO : QUOT202011-000058(00)
DATE : 19/11/2020
POLICY NO : 999995580
VEH REG NO : GBH5253M
MAKE/MODEL : MERCEDES VITO
CHASSIS NO : WDF44760323328432
ENGINE NO : 65195034177790
REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBH5253M

| Description | Quantity | Unit Price | | Amount | |
|--|---------------|-------------------|------------|----------|---|
| | | | SS | | |
| | | | SS | SS | |
| | <i>Repair</i> | 1 | 380.00 | 380.00 | X |
| 35 Front bumper reinforcement | 2 | 80.00 | <i>mit</i> | 160.00 | ✓ |
| 36 Front bumper carrier - RH / LH | 2 | 48.00 | <i>CM</i> | 96.00 | ✓ |
| 37 Front bumper side retainer - RH / LH | 1 | 20.00 | <i>mit</i> | 20.00 | ✓ |
| 38 Front bumper towing cover | 1 | 24.00 | <i>mit</i> | 24.00 | ✓ |
| 39 Front bumper strut - LH | 1 | 48.00 | <i>mit</i> | 48.00 | ✓ |
| 40 Front bumper strut - centre | 1 | <i>R</i> 185.00 | | 185.00 | ✓ |
| 41 Front bumper lower cross member | 1 | <i>CM</i> 125.00 | | 125.00 | ✓ |
| 42 Front bumper under cover | 15 | <i>m</i> 5.50 | | 82.50 | ✓ |
| 43 Front bumper clips | 1 | 480.00 | | 480.00 | ? |
| 44 Air-con condenser | 1 | 108.00 | | 108.00 | ? |
| 45 Air-con condenser support frame | 1 | 420.00 | | 420.00 | ? |
| 46 Radiator assy | 1 | 680.00 | | 680.00 | ? |
| 47 Radiator auto fan assy | 2 | 55.00 | | 110.00 | ? |
| 48 Radiator guide - RH / LH | 1 | 95.00 | | 95.00 | ? |
| 49 Radiator lower cover | 2 | 28.00 | | 56.00 | ? |
| 50 Radiator support - RH / LH | 2 | 12.00 | | 24.00 | ? |
| 51 Radiator top clips - RH / LH | 2 | 30.00 | | 60.00 | ? |
| 52 Radiator top bearing - RH / LH | 1 | 580.00 | | 580.00 | ? |
| 53 Inter-cooler assy | 1 | 168.00 | | 168.00 | ? |
| 54 Inter-cooler hose - LH | 2 | 520.00 | <i>R</i> | 1,040.00 | ✓ |
| 55 Front shock absorber - LH / RH | 1 | 218.00 | | 218.00 | ? |
| 56 Front shock absorber coil spring - LH | 1 | 128.00 | | 128.00 | ? |
| 57 Front shock absorber spring plate - LH | 1 | 48.00 | | 48.00 | ? |
| 58 Front shock absorber bellow - LH | 1 | 68.00 | <i>m</i> | 68.00 | ✓ |
| 59 Front shock absorber buffer stopper - LH | 1 | 63.00 | <i>m</i> | 63.00 | ✓ |
| 60 Front shock absorber plain bearing - LH | 1 | 188.00 | <i>m</i> | 188.00 | ✓ |
| 61 Front shock absorber support pushing - LH | 1 | 6.00 | <i>mit</i> | 6.00 | ✓ |
| 62 Front shock absorber nut - LH | 1 | 22.00 | <i>mit</i> | 22.00 | ✓ |
| 63 Front shock absorber dust protection cap - LH | 2 | <i>NSR</i> 720.00 | | 1,440.00 | ✓ |
| 64 Front control arm - LH / RH | 2 | 1,350.00 | <i>R</i> | 2,700.00 | ✓ |
| 65 Front knuckle arm (with hup) - LH / RH | 1 | 185.00 | | 185.00 | ? |
| 66 Front brake pad (set) | 2 | 175.00 | <i>mit</i> | 350.00 | ✓ |
| 67 Brake disc rotor - LH | 1 | 26.00 | <i>T</i> | 26.00 | ✓ |
| 68 Front brake sensor | 1 | | | | |



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 3

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 30/10/2020

ESTIMATE

NO : QUOT202011-000058(00)

DATE : 19/11/2020

POLICY NO : 999995580

VEH REG NO : GBH5253M

MAKE/MODEL : MERCEDES VITO

CHASSIS NO : WDF44760323328432

ENGINE NO : 65195034177790

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBH5253M

| Description | Quantity | Unit Price | Amount | | |
|---|----------|------------|-----------|-----------|---|
| | | | S\$ | S\$ | |
| 69 Steering tie-rod - LH | 1 | mit 125.00 | 125.00 | 125.00 | ✓ |
| 70 Steering tie-rod end - LH | 1 | mit 125.00 | 125.00 | 125.00 | ✓ |
| 71 Steering rack cover | 1 | 70.00 | mit 70.00 | 70.00 | ✓ |
| 72 Front wheel rim - LH / RH | 2 | 590.00 | 1,180.00 | 1,180.00 | ✓ |
| 73 Rear sport rim - RH | 1 | 590.00 | 590.00 | 590.00 | ✓ |
| 74 Front door frame - LH | 1 | 950.00 | 950.00 | 950.00 | ✓ |
| 75 Front door frame A pillar reinforcement (outer) - LH | 1 | 248.00 | 248.00 | 248.00 | ✓ |
| 76 Front door frame B pillar reinforcement (outer) - LH | 1 | 184.00 | 184.00 | 184.00 | ✓ |
| 77 Front door - RH / LH | 2 | 950.00 | 1,900.00 | 1,900.00 | ✓ |
| 78 Front door inner trimboard - LH | 1 | 480.00 | 480.00 | 480.00 | ✓ |
| 79 Front door trimboard clips - LH | 15 | 5.50 | 82.50 | 82.50 | ✓ |
| 80 Front door weatherstrip - LH / RH | 2 | 168.00 | 336.00 | 336.00 | ✓ |
| 81 Front door regulator gear - LH | 1 | 550.00 | 550.00 | 550.00 | ✓ |
| 82 Front door hinges - RH / LH | 4 | 115.00 | 460.00 | 460.00 | ✓ |
| 83 Front door checker - LH / RH | 2 | 78.00 | 156.00 | 156.00 | ✓ |
| 84 Front door seperation seal - LH | 1 | 28.00 | 28.00 | 28.00 | ✓ |
| 85 Front door inner lock - LH | 1 | 185.00 | 185.00 | 185.00 | ✓ |
| 86 Front door striker - LH | 1 | 53.00 | 53.00 | 53.00 | ✓ |
| 87 Front door step garnish - LH | 1 | 155.00 | 155.00 | 155.00 | ✓ |
| 88 Front door outer handle - RH | 1 | 78.00 | 78.00 | 78.00 | ✓ |
| 89 Front door glass - RH | 1 | 185.00 | 185.00 | 185.00 | ✓ |
| 90 Front door glass outer moulding - RH | 1 | 58.00 | 58.00 | 58.00 | ✓ |
| 91 Front door top moulding - RH | 1 | 118.00 | 118.00 | 118.00 | ✓ |
| 92 Side mirror assy - RH | 1 | 850.00 | 850.00 | 850.00 | ✓ |
| 93 Sliding door - RH / LH | 2 | 1,350.00 | 2,700.00 | 2,700.00 | ✓ |
| 94 Sliding door weatherstrip - RH / LH | 2 | 198.00 | 396.00 | 396.00 | ? |
| 95 Taillamp assy - RH | 1 | 550.00 | 550.00 | 550.00 | ✓ |
| | | | 51,218.00 | 51,218.00 | |
| | | | Add 10% | 3,421.20 | |
| | | | | 54,639.20 | |
| SPECIAL NET | | | | | |
| 96 Front windscreen sealant | 1 | 60.00 | 60.00 | 60.00 | ✓ |
| 97 Radiator coolant | 1 | 40.00 | 40.00 | 40.00 | ✓ |
| 98 Front tyre - LH / RH | 2 | 418.00 | 836.00 | 836.00 | ✓ |
| 99 Front number plate | 1 | 40.00 | 40.00 | 40.00 | ✓ |



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 4

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000 FAX : 6415 3723
YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 30/10/2020

ESTIMATE

NO : QUOT202011-000058(00)
DATE : 19/11/2020
POLICY NO : 999995580
VEH REG NO : GBH5253M
MAKE/MODEL : MERCEDES VITO
CHASSIS NO : WDF44760323328432
ENGINE NO : 65195034177790
REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBH5253M

| Description | Quantity | Unit Price | | Amount |
|---|----------|---------------------|----------------------|----------------|
| | | S\$ | S\$ | S\$ |
| 100 ERP bracket | 1 | 26.00 | 26.00 | 26.00 ✓ |
| | | | | 1,002.00 |
| LABOUR | | | | |
| 101 To remove and refit front windscreen glass | 1 | 150.00 | 150.00 | 150.00 120d |
| 102 To remove and refit roof lining | 1 | 150.00 | 150.00 | 150.00 120d |
| 103 To remove and refit front dashboard assy, meter and grove compartment | 1 | 350.00 | 350.00 | 350.00 250d |
| 104 To remove and refit air-con condenser, radiator, inter-cooler assy and refill air-con gas | 1 | 280.00 | 280.00 | 280.00 120d |
| 105 To transfer both side front door and both side sliding door interior mechanism and glass to new door and sliding door | 1 | 600.00 | 600.00 | 600.00 180d |
| 106 To check and rectify wiring systems | 1 | 80.00 | 80.00 | 80.00 40d |
| 107 To remove and refit steering air bag, passenger air bag, airbag control unit, front both side and centre safety belt | 1 | 550.00 | 550.00 | 550.00 280d |
| 108 To remove and refit battery cut off switch | 1 | 150.00 | 150.00 | 150.00 ? |
| 109 To lift-up engine and gear box to facilitates the repairs | 1 | 1,500.00 | 1,500.00 | 1,500.00 ? |
| 110 To remove and refit RH / LH front undercarriage | 1 | 680.00 | 680.00 | 680.00 400d |
| 111 To panel beat and straighten RH front chassis frame, RH front door pillar, RH rear fender, to cut and weld roof top panel, LH front door frame, LH front door frame A & B inner panel, LH front wheel house, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same | 1 | 3,800.00 | 3,800.00 | 3,800.00 3200d |
| 112 To putty and spray paint on affected areas | 1 | 3,500.00 | 3,500.00 | 3,500.00 2600d |
| 113 To re-programme and coding all faulty code (online) | 1 | 580.00 | 580.00 | 580.00 ? |
| 114 To check wheel alignment | 1 | 100.00 | 100.00 | 100.00 60d |
| | | | | 12,470.00 |
| | | TOTAL | S\$ 68,111.20 | |
| | | ADD GST @ 7% | 4,767.78 | |
| | | GRAND TOTAL | S\$ 72,878.98 | |

SINGAPORE DOLLAR SEVENTY-TWO THOUSAND EIGHT HUNDRED SEVENTY-EIGHT AND CENTS NINETY-EIGHT ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-----------------------|
| Date Of Report | 01/11/2020 19:04 |
| Date Of Accident | 30/10/2020 02:00 |
| Exact Location Of Accident | ALONG ESPLANADE DRIVE |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|--|
| Vehicle Registration Number | GBH5253M |
| Insured/Policyholder | |
| Name Of Registered Owner | DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. |
| Co Reg No | 1XXXXX778Z |
| Email Address | NORAZMAN.ABDUL_AZIZ@DAIMLER.COM |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-68498118 |

Vehicle Particulars

| | |
|--|--|
| Manufacturer | MERCEDES-BENZ |
| Model | VITO 114 CDI PANEL VAN LONG AT ABS 5DR |
| Exact Purpose for which vehicle was being used at time of accident | COMMERCIAL |
| Are you claiming under your own insurance policy for repair to your vehicle? | YES |
| If No, Please state action to be taken | |
| Vehicle Category | COMMERCIAL VEHICLE |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | YES |
| Policy Number | 999995580 |
| Cover Note Number | NA |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | SAFUAN BIN KAMARODIN |
| NRIC No | SXXXX577J |
| Date Of Birth | 21/09/1982 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 16/09/2010 |
| Driving Experience | 10 YEARS AND 1 MONTH |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-88176576 |
| Fax Number | |
| Contact Number | |
| E-Mail Address | SAFUAN.2109@GMAIL.COM |

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

778Z

Vehicle Details

Vehicle No.:

GBH5253M

Vehicle to be Exported:

No

Intended Deregistration Date:

30 Nov 2020

Vehicle Make:

MERCEDES BENZ

Vehicle Model:

VITO 114 CDI PANEL VAN LONG AT ABS 5DR

Primary Colour:

Blue

Manufacturing Year:

2017

Engine No.:

65195034177790

Chassis No.:

WDF44760323328432

Maximum Power Output:

-

Open Market Value:

\$37,761.00

Original Registration Date:

29 Jun 2018

First Registration Date:

29 Jun 2018

Transfer Count:

0

Actual ARF Paid:

\$1,889.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

28 Jun 2028

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$32,001.00

COE Rebate Amount:

\$24,249.00

Total Rebate Amount:

\$24,249.00

The information contained herein is correct as at 20 Nov 2020

OK