



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 30/10/2020

ESTIMATE

NO : QUOT202011-000058(00)

DATE : 19/11/2020

POLICY NO : 999995580

VEH REG NO : GBH5253M

MAKE/MODEL : MERCEDES VITO

CHASSIS NO : WDF44760323328432

ENGINE NO : 65195034177790

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBH5253M

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Front windscreen glass	1	720.00	720.00
2 Roof top panel	1	1,550.00	1,550.00
3 Roof top lining	1	920.00	920.00
4 Dashboard assy	1	1,150.00	1,150.00
5 Steering air bag	1	2,450.00	2,450.00
6 Passenger air bag	1	2,450.00	2,450.00
7 Air bag control unit	1	980.00	980.00
8 Front safety belt - RH / LH	2	800.00	1,600.00
9 Front safety belt buckle - RH / LH	2	220.00	440.00
10 Front safety belt adjuster - RH / LH	2	125.00	250.00
11 Front safety belt - centre	1	800.00	800.00
12 Front safety belt buckle - centre	1	120.00	120.00
13 Battery cut off switch	1	350.00	350.00
14 Bonnet	1	850.00	850.00
15 Bonnet hinge - RH / LH	2	68.00	136.00
16 Bonnet cable	1	55.00	55.00
17 Support panel	1	280.00	280.00
18 Support panel top garnish	1	95.00	95.00
19 Support panel bracket - LH	1	24.00	24.00
20 Brace panel	1	78.00	78.00
21 Front wheel house panel -- LH	1	680.00	680.00
22 Front chassis frame -- LH	1	2,500.00	2,500.00
23 Front longitudinal member - LH	1	955.00	955.00
24 Front fender - RH / LH	2	550.00	1,100.00
25 Front fender inner shield - RH / LH	2	125.00	250.00
26 Front fender inner shield flap - LH	1	30.00	30.00
27 Front fender inner shield clips - RH / LH	40	5.50	220.00
28 Front fender signal lamp - LH	1	38.00	38.00
29 Headlamp assy - RH	1	850.00	850.00
30 Headlamp assy - LH	1	1,800.00	1,800.00
31 Headlamp control unit - LH	1	655.00	655.00
32 Headlamp control module - LH	1	950.00	950.00
33 Front bumper	1	750.00	750.00
34 Front bumper reinforcement	1	420.00	420.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 30/10/2020

ESTIMATE

NO : QUOT202011-000058(00)

DATE : 19/11/2020

POLICY NO : 999995580

VEH REG NO : GBH5253M

MAKE/MODEL : MERCEDES VITO

CHASSIS NO : WDF44760323328432

ENGINE NO : 65195034177790

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBH5253M

Description	Quantity	Unit Price	Amount
		S\$	S\$
35 Front bumper reinforcement	1	380.00	380.00
36 Front bumper carrier - RH / LH	2	80.00	160.00
37 Front bumper side retainer - RH / LH	2	48.00	96.00
38 Front bumper towing cover	1	20.00	20.00
39 Front bumper strut - LH	1	24.00	24.00
40 Front bumper strut - centre	1	48.00	48.00
41 Front bumper lower cross member	1	185.00	185.00
42 Front bumper under cover	1	125.00	125.00
43 Front bumper clips	15	5.50	82.50
44 Air-con condenser	1	480.00	480.00
45 Air-con condenser support frame	1	108.00	108.00
46 Radiator assy	1	420.00	420.00
47 Radiator auto fan assy	1	680.00	680.00
48 Radiator guide - RH / LH	2	55.00	110.00
49 Radiator lower cover	1	95.00	95.00
50 Radiator support - RH / LH	2	28.00	56.00
51 Radiator top clips - RH / LH	2	12.00	24.00
52 Radiator top bearing - RH / LH	2	30.00	60.00
53 Inter-cooler assy	1	580.00	580.00
54 Inter-cooler hose - LH	1	168.00	168.00
55 Front shock absorber - LH / RH	2	520.00	1,040.00
56 Front shock absorber coil spring - LH	1	218.00	218.00
57 Front shock absorber spring plate - LH	1	128.00	128.00
58 Front shock absorber bellow - LH	1	48.00	48.00
59 Front shock absorber buffer stopper - LH	1	68.00	68.00
60 Front shock absorber plain bearing - LH	1	63.00	63.00
61 Front shock absorber support pushing - LH	1	188.00	188.00
62 Front shock absorber nut - LH	1	6.00	6.00
63 Front shock absorber dust protection cap - LH	1	22.00	22.00
64 Front control arm - LH / RH	2	720.00	1,440.00
65 Front knuckle arm (with hup) - LH / RH	2	1,350.00	2,700.00
66 Front brake pad (set)	1	185.00	185.00
67 Brake disc rotor - LH	2	175.00	350.00
68 Front brake sensor	1	26.00	26.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 3

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 30/10/2020

ESTIMATE

NO : QUOT202011-000058(00)

DATE : 19/11/2020

POLICY NO : 999995580

VEH REG NO : **GBH5253M**

MAKE/MODEL : MERCEDES VITO

CHASSIS NO : WDF44760323328432

ENGINE NO : 65195034177790

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBH5253M

Description	Quantity	Unit Price	Amount
		S\$	S\$
69 Steering tie-rod - LH	1	125.00	125.00
70 Steering tie-rod end - LH	1	125.00	125.00
71 Steering rack cover	1	70.00	70.00
72 Front wheel rim - LH / RH	2	590.00	1,180.00
73 Rear sport rim - RH	1	590.00	590.00
74 Front door frame - LH	1	950.00	950.00
75 Front door frame A pillar reinforcement (outer) - LH	1	248.00	248.00
76 Front door frame B pillar reinforcement (outer) - LH	1	184.00	184.00
77 Front door - RH / LH	2	950.00	1,900.00
78 Front door inner trimboard - LH	1	480.00	480.00
79 Front door trimboard clips - LH	15	5.50	82.50
80 Front door weatherstrip - LH / RH	2	168.00	336.00
81 Front door regulator gear - LH	1	550.00	550.00
82 Front door hinges - RH / LH	4	115.00	460.00
83 Front door checker - LH / RH	2	78.00	156.00
84 Front door separation seal - LH	1	28.00	28.00
85 Front door inner lock - LH	1	185.00	185.00
86 Front door striker - LH	1	53.00	53.00
87 Front door step garnish - LH	1	155.00	155.00
88 Front door outer handle - RH	1	78.00	78.00
89 Front door glass - RH	1	185.00	185.00
90 Front door glass outer moulding - RH	1	58.00	58.00
91 Front door top moulding - RH	1	118.00	118.00
92 Side mirror assy - RH	1	850.00	850.00
93 Sliding door - RH / LH	2	1,350.00	2,700.00
94 Sliding door weatherstrip - RH / LH	2	198.00	396.00
95 Taillamp assy - RH	1	550.00	550.00
			51,218.00
		Add 10%	3,421.20
			<u>54,639.20</u>
SPECIAL NET			
96 Front windscreen sealant	1	60.00	60.00
97 Radiator coolant	1	40.00	40.00
98 Front tyre - LH / RH	2	418.00	836.00
99 Front number plate	1	40.00	40.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 4

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 30/10/2020

ESTIMATE

NO : QUOT202011-000058(00)

DATE : 19/11/2020

POLICY NO : 999995580

VEH REG NO : GBH5253M

MAKE/MODEL : MERCEDES VITO

CHASSIS NO : WDF44760323328432

ENGINE NO : 65195034177790

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBH5253M

Description	Quantity	Unit Price	Amount
		S\$	S\$
100 ERP bracket	1	26.00	26.00
			1,002.00
LABOUR			
101 To remove and refit front windscreen glass	1	150.00	150.00
102 To remove and refit roof lining	1	150.00	150.00
103 To remove and refit front dashboard assy, meter and grove compartment	1	350.00	350.00
104 To remove and refit air-con condenser, radiator, inter-cooler assy and refill air-con gas	1	280.00	280.00
105 To transfer both side front door and both side sliding door interior mechanism and glass to new door and sliding door	1	600.00	600.00
106 To check and rectify wiring systems	1	80.00	80.00
107 To remove and refit steering air bag, passenger air bag, airbag control unit, front both side and centre safety belt	1	550.00	550.00
108 To remove and refit battery cut off switch	1	150.00	150.00
109 To lift-up engine and gear box to facilitates the repairs	1	1,500.00	1,500.00
110 To remove and refit RH / LH front undercarriage	1	680.00	680.00
111 To panel beat and straighten RH front chassis frame, RH front door pillar, RH rear fender, to cut and weld roof top panel, LH front door frame, LH front door frame A & B inner panel, LH front wheel house, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	3,800.00	3,800.00
112 To putty and spray paint on affected areas	1	3,500.00	3,500.00
113 To re-programme and coding all faulty code (online)	1	580.00	580.00
114 To check wheel alignment	1	100.00	100.00
			12,470.00
		TOTAL	S\$ 68,111.20
		ADD GST @ 7%	4,767.78
		GRAND TOTAL	S\$ 72,878.98

SINGAPORE DOLLAR SEVENTY-TWO THOUSAND EIGHT HUNDRED SEVENTY-EIGHT AND CENTS NINETY-EIGHT ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/11/2020 19:04
Date Of Accident	30/10/2020 02:00
Exact Location Of Accident	ALONG ESPLANADE DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH5253M
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	1XXXXX778Z
Email Address	NORAZMAN.ABDUL_AZIZ@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68498118
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	VITO 114 CDI PANEL VAN LONG AT ABS 5DR
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	NA
Driver	
Name of Driver	SAFUAN BIN KAMARODIN
NRIC No	SXXXX577J
Date Of Birth	21/09/1982
Occupation	OUTDOOR
Date Of Driving Pass	16/09/2010
Driving Experience	10 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-88176576
Fax Number	
Contact Number	
Email Address	SAFUAN.2109@GMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was travelling along ESPLANADE DRIVE it was a 4 lane traffic and my vehicle was positioned in the 2nd lane and suddenly I dozed off and therefore my vehicle collided onto the left side road railing and overturn. I was not conveyed by ambulance but I sustained some injuries to my right elbow and right knee. Advised driver to make police report as he was given more den 3 days of mc.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	RAILING
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	SAFUAN BIN KAMARODIN
Approximate Age	
Injuries Sustain	INJURIES RIGHT ELBOW AND RIGHT KNEE
Injured person in which vehicle?	GBH5253M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


1 Nov 2020

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SAIFULLAH S/O SYED MASOOD

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

Lined area for describing the circumstances of the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SAIFULLAH S/O SYED MASOOD

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


Driving License



Driving License



Identification Card



134





CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1950
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

MZ 400

COMPREHENSIVE COMMERCIAL MOTOR	OWN DAMAGE EXCESS	SS\$1,400.00 (1)
CERTIFICATE NO. 999993880/100862124-00000	WINDSCREEN EXCESS	SS\$100.00
	<small>(for policies with effect from 1st November 2002)</small>	
	SUM INSURED	SS\$1.00
	INSURING WITH COE/PARF	YES
1) VEHICLE REGISTRATION NO.	GBH5253M	
2) NAME OF INSURED	Daimler Fleet Management Singapore Pte Ltd	
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT	1 Jan 2020	
4) DATE OF EXPIRY OF INSURANCE	31 Dec 2020	
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *		
<p>1) Any drivers who is driving on the Insured's order or with their permission. 2) Additional Excess \$1500 or \$2500 applies to authorised drivers age below 21 or above 65 years old and or less than 2 years driving experience. Refer to policy for the applicable excess</p>		
<p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p>		
6) LIMITATION AS TO USE *		
<p>Use for the carriage of passengers or goods in connection with the Policyholder's business. Use for social, domestic, pleasure purposes and business purposes of any person to whom the Vehicle is hired. This Policy does not cover</p> <p>1) use for driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, 2) use whilst drawing a trailer except the towing (other than for reward) of anyone disabled using a mechanically propelled vehicle; and 3) use for the carriage of passengers for hire or reward by any person to whom the Vehicle is hired.</p> <p>In the event of accident claim, the repairs to the Vehicle must be carried out by either one of our AIG Authorized Repairers or a particular Repairer approved by AIG</p>		
LOSS OF USE	NOT INCLUDED	
* NAMED DRIVER	N/A	
HIRE PURCHASE COMPANY	NA	
<p>* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings</p>		

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 17 Feb 2020

AIG ASIA PACIFIC INSURANCE PTE. LTD.

030023-000
JARDINE LLOYD THOMPSON PTE LTD
138 MARKET STREET
#07-01 CAPITAGREEN
SINGAPORE 048946



Authorised Representative

ORIGINAL

SSCDEK