

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 08 Jan 2021

## **Preliminary Advice**

Vehicle No	: GBH5253M	Accident Date	: 30/10/2020
Make	: MERCEDES-BENZ VITO 114	Policy No.	: 0999993880
Assignment Date	: 23/11/2020	Excess	: S\$0.00
Date of Inspection	: 23/11/2020	Est. Duration of Repair	: 35
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident. The undercarriage & body structure affected due to collision.

Repairer's Estimate (Gross)	:S\$	68,111.20
Revised Amount	:S\$	51,525.80
Check Items (Estimated)	:S\$	9,986.10
Total	:S\$	61,511.90
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	24,249.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,751.00

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Margin for repair is \$42,751.00. The same similar make / model was no longer in production / Available.