



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/ANG SAU SHIUN
	Reg No/Reg Date	SJW7576U / 29/08/201
	Date In/Mileage	/ 43503
	Chassis No	KNAF3416MK5012718
	Engine No	G4FGJH702736
	Make/Model	KIA/CERATO 1.6 A SX G335
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	23/11/2020/ 10:55	QUD	247 / DonBong	24693			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1200.00
RENEW ACCIDENT DAMAGED PARTS ON LH FRONT FENDER, FRONT BUMPER, REPAIR LH FRONT DOOR PANEL, REPAIR REAR BUMPER								✓ 60.00
E PNT88000								60.00
REMOVE AND INSTALL PARKING ASSIST FOR FRONT								✓ 60.00
E PNT88000								60.00
REMOVE AND INSTALL PARKING ASSIST FOR REAR								✓ 2400.00
E PNT98000								2400.00
PAINT WORK SPRAY FRONT BUMPER, LH FRONT FENDER. LH FRONT DOOR, REAR BUMPER AND AFFECTED PORTION								✓ 80.00
M SUNDRY								80.00
PERFORM RUST PREVENTION								✓ 30.00
A 54900099								30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								✓ 120.00
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								✓ 120.00
A WHEELALIGNMENTBP								120.00
To Conduct Computerize Full Wheel Alignment								✓ 840.00
M SUNDRY								840.00
SUPPLY LH FRONT TIRE & LH REAR TIRE								✓ 60.00
M SUNDRY								60.00
LABOUR RENEW BOTH LH SPORT RIM INCLUDING BALANCING								✓ 600.00
A 50000001								600.00
RENEW FRONT AND REAR UNDERCARRIAGE DAMAGES								✓ 50.00
M SUNDRY								50.00
SUNDRIES								1768.00
M LAMP ASSY-HEAD,LH					1.00	2210.00	20.00	✓ 1768.00
M LAMP ASSY-HEAD,RH					1.00	2210.00	20.00	✓ 1768.00
M PANEL-FENDER,LH					1.00	430.00	20.00	✓ 344.00
M INSULATOR-FENDER LH					1.00	27.00	20.00	✓ 21.60
M GUARD ASSY-FRONT WHEEL,LH					1.00	95.00	20.00	✓ 76.00
M CLIP					10.00	1.00	20.00	✓ 8.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/ANG SAU SHIUN
	Reg No/Reg Date	SJW7576U / 29/08/201
	Date In/Mileage	/ 43503
	Chassis No	KNAF3416MK5012718
	Engine No	G4FGJH702736
	Make/Model	KIA/CERATO 1.6 A SX G335
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	23/11/2020/ 10:55	QUD	247 / DonBong	24693
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BRACKET-FR BUMPER UPR SIDE MTG		1.00	22.00	20.00	17.60
M BRACKET-FR BUMPER UPR SIDE MTG		1.00	22.00	20.00	17.60
M LAMP ASSY-SIDE REPEATER,LH		1.00	143.00	20.00	114.40
M MOULDING-FRONT BUMPER,LH		1.00	43.00	20.00	34.40
M LAMP ASSY-FRONT FOG,LH		1.00	303.00	20.00	242.40
M RETAINER-BUMPER SIDE MTG		1.00	1.00	20.00	0.80
M COVER-FR BUMPER		1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER		1.00	485.00	20.00	388 1552.00
M ULTRASONIC SENSOR ASSY-P.A.S		1.00	163.00	20.00	130.40
M ULTRASONIC SENSOR ASSY-P.A.S		1.00	163.00	20.00	130.40
M ULTRASONIC SENSOR ASSY-P.A.S		1.00	163.00	20.00	130.40
M ULTRASONIC SENSOR ASSY-P.A.S		1.00	163.00	20.00	130.40
M ORNAMENT-KIA NO.115		1.00	32.00	20.00	25.60
M PANEL ASSY-UNDER COVER		1.00	117.00	20.00	93.60
M CLIP UNDER COVER		12.00	1.00	20.00	9.60
M LH FRONT WHEEL ASSY-ALUMINIUM		1.00	926.00	20.00	740.80
M HUB ASSY-FR WHEEL		1.00	436.00	20.00	348.80
M COVER-FR BRAKE DISC DUST LH		1.00	29.00	20.00	23.20
M KNUCKLE-FRONT AXLE,LH		1.00	350.00	20.00	280.00
M GEAR ASSY-STEERING		1.00	770.00	20.00	616.00
M LH LINK-STABILIZER		1.00	72.00	20.00	57.60
M RH LINK-STABILIZER		1.00	72.00	20.00	57.60
M STRUT ASSY-FR,LH		1.00	280.00	20.00	224.00
M STRUT ASSY-FR,RH		1.00	280.00	20.00	224.00
M BEARING-STRUT		1.00	86.00	20.00	68.80
M BEARING-STRUT		1.00	86.00	20.00	68.80
M INSULATOR ASSY-STRUT		1.00	85.00	20.00	68.00
M INSULATOR ASSY-STRUT		1.00	85.00	20.00	68.00
M CROSSMEMBER COMPL		1.00	1156.00	20.00	924.80
M ARM COMPLETE-FR LWR,LH		1.00	286.00	20.00	228.80
M ARM COMPLETE-FR LWR,RH		1.00	286.00	20.00	228.80
M STAY LH		1.00	22.00	20.00	17.60
M STAY RH		1.00	22.00	20.00	17.60

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/ANG SAU SHIUN
	Reg No/Reg Date	SJW7576U / 29/08/201
	Date In/Mileage	/ 43503
	Chassis No	KNAF3416MK5012718
	Engine No	G4FGJH702736
	Make/Model	KIA/CERATO 1.6 A SX G335
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	23/11/2020/ 10:55	QUD	247 / DonBong	24693

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M TORSION AXLE COMPLETE	1.00	1031.00	20.00	824.80
M UNDER COVER	1.00	143.00	20.00	114.40
M SHOCK ABSORBER ASSY-REAR	1.00	231.00	20.00	184.80
M SHOCK ABSORBER ASSY-REAR	1.00	231.00	20.00	184.80
M HUB & BEARING ASSY-RR	1.00	437.00	20.00	349.60
M LH REAR WHEEL ASSY-ALUMINIUM	1.00	926.00	20.00	740.80

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Tanpin 97475144SURVEYOR SIGNATURE: [Signature]DATE: 23/11/20 01:50REMARKS: Not Authorise Ex: tbaResurvey before painttanpin@lkkauto.com 07days

Confirm &amp; accepted by

Nett	19,404.00
7% GST on	1358.28
<b>Total Payable</b>	<b>20,762.28</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.