

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0892/2020/NS
DATE : 19-Nov-20
WIP : 58154

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Hi Adrian

4 days - ok - jb - 8 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR NGUYEN THI THUY HANG
ADDRESS : 60 PHOENIX ROAD
SINGAPORE 668198
TELEPHONE : HP +65 87873588
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900114968-01
VEHICLE NO : **SML 3588 J**
MODEL CODE : AUDI Q8 3.0 TFSI QU 4MN0X
MODEL YEAR : 28/6/2019
ENGINE NO : DCB 067483
CHASSIS NO : WAUZZZF11KD015567
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Nov-20
PLACE OF ACCIDENT : JEM MALL B1 CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 3588 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS	
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00		
2	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	\$	280.00
3	TO DISMANTLE REAR BUMPER AND RHS REAR DOOR. TO RENEW RHS REAR DOOR. TO REPAIR RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,150.00	\$	900.00
4	TO REPRAY REAR TOP BUMPER, REAR LOWER BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR COVER, RHS REAR DOOR WHEEL ARCH TRIM, BOTH REAR WHEEL ARCH TRIMS.	\$ 5,500.00	\$	1,900.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 9,482.00	\$ 3,272.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3588 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR DOOR - RH		\$ 3,937.00	\$ 3,149.60
2	REAR DOOR OUTER SEAL - RH	NEC	\$ 170.00	\$ 135.60
3	BONDING AGENT	NEC	\$ 47.00	
4	CLEANING SOLUTION	NEC	\$ 65.00	
5	REAR DOOR ATTACHMENT PARTS		\$ 209.00	
6	REAR DOOR CATCH		\$ 104.00	
7	REAR DOOR SEAL OUTER - RH		\$ 250.00	\$ 200.00
8	SILL PANEL SEAL - RH		\$ 250.00	
9	REAR DOOR COVER - RH		\$ 502.00	\$ 401.20
10	REAR DOOR WHEEL ARCH TRIM - RH		\$ 194.00	\$ 155.20
11	REAR FENDER WHEEL ARCH TRIM - LH/RH	2	\$ 746.00	\$ 298.00
12	REAR WHEEL COVER - RH		\$ 115.00	
13	SUNDRIES		\$ 300.00	\$ 95.68
TOTAL SPARE PARTS		:	\$ 6,889.00	\$ 4,435.28
TOTAL LABOUR CHARGES		:	\$ 9,482.00	\$ 3,272.00
GRAND TOTAL		:	\$ 16,371.00	\$ 7,707.28

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-13/01/21



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT