

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0891/2020/NS
DATE : 19-Nov-20
WIP : 58159

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

6 days to repair this vehicle.

22/02/2021 - Carrine

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR GAN WAI SENG
ADDRESS : BLK 87 ZION ROAD
#24-172
SINGAPORE 160087
TELEPHONE : HP +65 97964880
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070054898
VEHICLE NO : **SDL 186 L**
MODEL CODE : AUDI Q3 SPORTSBACK 1.4 TFS
MODEL YEAR : 25/3/2020
ENGINE NO : CZD 891580
CHASSIS NO : WAUZZZF31L1077314
MILEAGE : 3686KM
DATE IN : 18-Nov-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Nov-20
PLACE OF ACCIDENT : MARINE CRESCENT AND MARINE TERRACE
JUNCTION

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDL 186 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	\$ 280.00
3	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR. TO RENEW LHS FRONT FENDER AND LHS AND LHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	\$ 750.00
4	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, DOOR COVER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 3,500.00	\$ 1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 7,652.00	\$ 2,722.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDL 186 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT FENDER - LH		\$ 1,271.00	
2	FRONT FENDER ATTACHMENT PARTS		\$ 62.00	
3	FRONT FENDER BRACE - LH		\$ 87.00	
4	FRONT FENDER BRACKET - LH		\$ 31.00	
5	FRONT WHEEL HOUSING LINER - LH		\$ 237.00	
6	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 100.00	
7	FRONT WHEEL COVER - LH/RH	2	\$ 1,060.00	\$ 424.00
8	FRONT DOOR - LH		\$ 2,553.00	\$ 2,042.40
9	FRONT DOOR OUTER SEAL - LH	NEC	\$ 164.00	\$ 131.20
10	FRONT DOOR CATCH		\$ 119.00	
11	DOOR HINGE HALVES - LH UPPER		\$ 45.00	
12	DOOR HINGE HALVES - LH UPPER		\$ 45.00	
13	DOOR HINGE HALVES - LH LOWER		\$ 45.00	
14	DOOR HINGE HALVES - LH LOWER		\$ 45.00	
15	FRONT DOOR COVER - LH		\$ 366.00	\$ 292.80
16	SILL MEMBER TRIM - LH		\$ 177.00	
17	B PILLAR TRIM - LH		\$ 110.00	
18	SUNDRIES		\$ 300.00	\$ 3.36
TOTAL SPARE PARTS		:	\$ 6,817.00	\$ 2,893.76
TOTAL LABOUR CHARGES		:	\$ 7,652.00	\$ 2,722.00
GRAND TOTAL		:	\$ 14,469.00	\$ 5,615.76

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-13/01/21