

CHOON HOCK MOTOR TRADING CO

25 November 2020

*Not Authorized
11/11/2020
Running After Repair
3 days*

ESTIMATE REPAIR BILL ON SKB3355R TOYOTA SIENTA 7-SEATER 1.5X CVT

1 pce front bumper assy. *679.00*
1 pce front bumper reinforcement
1 pce front bumper sponge *162.*
1 pce front grille assy. *598.00*
1 pce headlamp RH
1 pce panel top garnish
1 pce 'TOYOTA' label

Bu	\$1,350.70	—
R	\$ 290.50	X
CM	\$ 185.20	—
RA	\$ 740.00	—
mg CM	\$ 969.20	—
CM	\$ 98.20	—
RA	\$ 70.00	—
	\$3,703.80	
less 25%	\$ 925.95	
	\$2,777.85	

S/NETT

1 pce no. plate
Wiring
Panel beating
Spray painting
Total amount :

Del	\$ 50.00	<i>455n</i>
	\$ 80.00	<i>201</i>
	\$ 600.00	<i>3601</i>
	\$ 600.00	<i>4201</i>
	\$4,107.95	NETT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: